

MAGNETIC PARTICLE EXAMINATION REPORT

Certificate No:	SAG-INS-2026-3480-1-AA	Date of Inspection:	12.02.2026
Job card No:	INSP-TS-3437	Time of Inspection:	08.00 AM
SAG work procedure:	SAG-OM-2021-28	Next Inspection:	11.08.2026


Customer/ Client:	TRUCK OMAN EQUIPMENT RENTAL LLC			Test Location:	ADAM
Reg no / Asset no:	3747 HA / PLM 1026			Serial No:	1049552563
Description:	FIFTH WHEEL MOUNTED BASE PLATE				
Previous Inspection:	NOT AVAILABLE				
Equipment	Serial Number	Due Date	Consumables	Batch No.	Exp. Date
Perm. Yoke	PY092CM	19/09/2026	White Contrast	241002	Oct-2027
Lux Meter	21079325	11/04/2026	Black Magnetic Ink	230604	Jun-2026
Exam Method	Mag. Method	Current Type	Lighting Type	Field Direction	Lighting
Wet	Continues	--	Visible	Longitudinal	Sunlight
Acc. Criteria	Light Value		Surface Condition	Surface Temp	
ASME SEC V article 7 , AWS D1.1PARTC CLAUSE 6.10	112.7 k lux		As Cleaned	30° c	

Inspected Item Picture



Area of testing:	LOAD-BEARING SURFACE
Inspection Result:	<ol style="list-style-type: none"> 1. VISUAL INSPECTION CARRIED OUT FOUND SATISFACTORY. 2. MPI TEST FOR LOAD BEARING SURFACE OF THE ITEM CARRIED OUT, NO INDICATION OF FAILURE FOUND, TEST RESULT ACCEPTABLE.

This is to certify that the above-mentioned items have been inspected and evaluated by the above signed inspector on mentioned location in Accordance to ASME Sec V, and Sultanate of Oman's regulations ministerial decree no 286/2008, year 2008, article (34). This Report cannot be reproduced in any form without the written consent of SAG AL SAHRA and cannot be used for any purpose other than those intended by SAG and involved party.

Name of the Competent Person:			
Al Muntaser Al Ghuzaili			
Name of Authorized person:			
Rajendra Jambukar			

