



الشركة الفنية لخدمات السلامة ش.م.م
SAFETY *technical* SERVICES CO. LTD.



MAGNETIC PARTICLE INSPECTION REPORT

| | | |
|--|--|--|
| Date of Thorough Examination: 01/03/2020 | Report number: K/42672/20/03/03 | Job no: 42672 |
| Name and Address of owner for whom the thorough examination was made: TRUCK OMAN EQUIPMENT RENTAL LLC SULTANATE OF OMAN | | Address of premises at which the examination was made: JUFFNAIN |
| Method: WET Surface Condition: Acceptable | Material: Carbon Steel Equipment: Permanent magnet Yoke | Test temperature: Ambient |
| Area Inspected (tick the appropriate box): <input type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others (top surface) | | |
| WHITE CONTRAST PAINT: Magnavis WCP | MAGNETISING METHOD: Wet suspension black ink | |
| BLACK MAGNETIC INK: Magnaflux 7HF | ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1 | |
| Description and identification of the equipment: <u>FIFTH WHEEL</u> | | |
| Make : JOST | | |
| Model: JSK38C | | |
| Serial no: 10524861 | | |
| Reg: 3748 HA | | |
| Owner id; PLM 1027 | | |
| Qty: 1nos | | |
| Date of Last MPI/ Cert No(If any):N/A | | |
| Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION | | |

| | | |
|---|--|--|
| Inspected by, Name & Signature : Malik Qualification : ASNT L2 | | Latest date by which next MPI must be carried out: 28/02/2021 |
| Name and address of employer of persons making and authenticating this report: SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. lifting@safetyoman.com | | |