

Inspected at:

Muscat

Owner:	TRUCK OMAN LLC.	Contractor:	PLM /BP
Make:	MAN: 2015	Type:	PRIME MOVER
Veh Reg. No:	3706 HA	Rated Capacity:	N/A
Veh Reg. Exp:	28-05-2018	Sticker No:	
		Khazzan No :	N/A
DDC Permit No:	NIL	ROP License No:	N/A
Exp Date:	NIL	Exp Date:	N/A
Drive/Op Name:	NIL	Km:	242013.2
Chassis no:	WMA34WZZ9FP062618	IVMS Provider:	FMSi.
Inspector:	D.SHETTY	Inspection Date:	31-05-2017

Ser	ITEM	P/F	Ser	ITEM	P/F
1	Seat belts	P	43	Brake system and components	P
2	Smoke emission	P	44	Reflective Rear markings	P
3	Road wheels and hubs	P	45	Position lamps	P
4	Tyre type	P	46	Reflectors	P
5	Tyres ,condition, pressure & age	P	47	Indicators	P
6	Side guards, under-run guards, bumpers	P	48	Headlamp aim	P
7	Spare wheel/jack/tools/shovel/vest	P	49	Headlamps	P
8	Trailer coupling	P	50	Brake lights	P
9	Mudguards	P	51	Service brake performance	P
10	Cab mountings	P	52	Secondary brake performance	P
11	Cab doors	P	53	Parking brake performance	P
12	Cab floor and Steps	P	54	Reversing alarm & lights	P
13	Seats & head restraints	P	55	High intensity rear lights	P
14	Bodywork/ladder fixed/access ladder	P	56	Revolving lights	P
15	Mirrors incl 'Blind Spot'	P	57	A/C unit	P
16	Windscreen glass vision, 100mm crack max	P	58	Battery condition	P
17	Windscreen wipers , washers	P	59	Fire ext for cab Exp: 02-04-2018	P
18	Speedometer	P	60	Fire ext for load Exp: 22-04-2018	P
19	Horn	P	61	First aid kit	P
20	Driving Controls & Driver Qualification	P	62	Hazard Warning Triangles x2	P
21	Tachograph or IVMS	P	63	Winch: annual certificate / condition	N/A
22	Steering wheel, column	P	64	Slings	N/A
23	Pressure / Vacuum warning	P	65	Oilfield headboard	N/A
24	Pressure / Vacuum build up	P	66	Speed limiter -by road test at kph : and speed limit logo 80/80	P
25	Mechanical brakes lever	N/A	67	Fluid levels	P
26	Service brake pedal	P	68	Radio/Music system – operating	P
27	Service brake operation	P	69	Fifth wheel assembly on prime mover	P
28	Hand brake control valves	P	70	Security of attachment of fifth wheel to prime-mover chassis	P
29	Chassis, sub-frame	P	71	High visibility vests X2	P
30	Electrical equipment , wiring	P	72	Pay load written	P
31	Engine, transmission mountings	P	73	Fuses Box unit	P
32	Oil leaks	P		<b>Additional Items :</b>	
33	Fuel tank(s) and systems	P	74	Tipper : ram operation , oil leaks	N/A
34	Exhaust	P	75	Tipper : hinge shaft and bearings	N/A
35	Exhaust break	P	76	HIAB SWL & inspection date stencil	N/A
36	Suspension	P	77	Annual SWL exp date	N/A
37	Shock absorbers	P	78	PLT certificate exp date	N/A
38	Axles, wheel bearings	P			
39	Steering assembly, including tie rod ends	P		<b>VOR = VEHICLE OFF ROAD</b>	
40	Transmission	P		<b>N/C = NOT CHECKED</b>	
41	Mechanical brake components	P		<b>N/F = NOT FITTED</b>	
42	Brake actuators	P		<b>N/A = NOT APPLICABLE</b>	

PASS

This vehicle is deemed fit to operate on BP business based on its roadworthiness condition at the time of conducting this inspection. It is the sole responsibility of the contractor to maintain the vehicle's fitness throughout the validity of the issued sticker. This fitness certificate doesn't waive the need for a pre-trip inspection & routine mechanical inspections which are the sole responsibility of the contractor.

Registration No:	3706 HA	Date of Inspection:	31/5/2017
Attach to Part 1 of the safety inspection report In check number column use checklist number from part 1 Repairs to be signed off by repair workshop supervisor VOR denotes Vehicle Off Road & not to be used until fault's are rectified			

Check No	Defect Details	Rectified
	NIL	

I confirm that the above defect have been rectified & the vehicle is now in a roadworthy condition			
Name of the Vehicle Inspector:	Dayananda Shetty.	Telephone No:	94465227
Date:	31/5/2017	Employee Number:	9022
Signature:			