

Inspected at:

Muscat

Owner:	PREMIER LOGISTICS	Contractor:	PREMIER / BP
Make:	MAN / 2015	Type:	PRIME MOVER
Veh Reg. No:	3706-HA	Rated Capacity:	W/L 29330 AS PER MULKIYA
Veh Reg. Exp:	15/06/2019	Sticker No:	H-17415
		Khazzan No :	
DDC Permit No:	NIL	ROP License No:	NIL
Exp Date:	NIL	Exp Date:	NIL
Drive/Op Name:	NIL	Km:	384749.7
Chassis no:	WMA34WZZ9FP062618	IVMS Provider:	FMSI
Inspector:	NOOR AL-BALUSHI	Inspection Date:	11/07/2018

Ser	ITEM	P/F	Ser	ITEM	P/F
1	Seat belts	P	43	Brake system and components	P
2	Smoke emission	P	44	Reflective Rear markings	P
3	Road wheels and hubs	P	45	Position lamps	P
4	Tyre type	P	46	Reflectors	P
5	Tyres ,condition, pressure & age	P	47	Indicators	P
6	Side guards, under-run guards, bumpers	P	48	Headlamp aim	P
7	Spare wheel/jack/tools/shovel/vest	P	49	Headlamps	P
8	Trailer coupling	P	50	Brake lights	P
9	Mudguards	P	51	Service brake performance	P
10	Cab mountings	P	52	Secondary brake performance	P
11	Cab doors	P	53	Parking brake performance	P
12	Cab floor and Steps	P	54	Reversing alarm & lights	P
13	Seats & head restraints	P	55	High intensity rear lights	P
14	Bodywork/ladder fixed/access ladder	P	56	Revolving lights	P
15	Mirrors incl 'Blind Spot'	P	57	A/C unit	P
16	Windscreen glass vision, 100mm crack max	P	58	Battery condition	P
17	Windscreen wipers , washers	P	59	Fire ext for cab Exp: 02/10/2018	P
18	Speedometer	P	60	Fire ext for load Exp: 04/04/2019	P
19	Horn	P	61	First aid kit	P
20	Driving Controls & Driver Qualification	P	62	Hazard Warning Triangles x2	P
21	Tachograph or IVMS	P	63	Winch: annual certificate / condition	N/A
22	Steering wheel, column	P	64	Slings	N/A
23	Pressure / Vacuum warning	P	65	Oilfield headboard	N/A
24	Pressure / Vacuum build up	P	66	Speed limiter -by road test at kph and speed limit logo:80/80	P
25	Mechanical brakes lever	N/A	67	Fluid levels	P
26	Service brake pedal	P	68	Radio/Music system – operating	P
27	Service brake operation	P	69	Fifth wheel assembly on prime mover	P
28	Hand brake control valves	P	70	Security of attachment of fifth wheel to prime-mover chassis	P
29	Chassis, sub-frame	P	71	High visibility vests X2	P
30	Electrical equipment , wiring	P	72	Pay load written: 29330 AS PER MULKIYA	P
31	Engine, transmission mountings	P	73	Fuses Box unit	P
32	Oil leaks	P		Additional Items :	
33	Fuel tank(s) and systems	P	74	Tipppers : ram operation , oil leaks	N/A
34	Exhaust	P	75	Tipppers : hinge shaft and bearings	N/A
35	Exhaust break	P	76	HIAB SWL & inspection date stencil	N/A
36	Suspension	P	77	Annual SWL exp date	N/A
37	Shock sbsorbers	P	78	PLT certificate exp date	N/A
38	Axles, wheel bearings	P			
39	Steering assembly, including tie rod ends	P		VOR = VEHICLE OFF ROAD	
40	Transmission	P		N/C = NOT CHECKED	
41	Mechanical brake components	P		N/F = NOT FITTED	
42	Brake actuators	P		N/A = NOT APPLICABLE	

PASS

This vehicle is deemed fit to operate on BP business based on its roadworthiness condition at the time of conducting this inspection. It is the sole responsibility of the contractor to maintain the vehicle's fitness throughout the validity of the issued sticker. This fitness certificate doesn't waive the need for a pre-trip inspection & routine mechanical inspections which are the sole responsibility of the contractor.

R/I

Registration No:	3706-HA	Date of Inspection:	11/7/2018
Attach to Part 1 of the safety inspection report In check number column use checklist number from part 1 Repairs to be signed off by repair workshop supervisor VOR denotes Vehicle Off Road & not to be used until fault's are rectified			

[illegible]

I confirm that the above defect have been rectified & the vehicle is now in a roadworthy condition

Name of the Vehicle Inspector: NOOR AL-BALUSHI

Telephone No: 94462607

Date: 11/7/2018

Employee Number: 9057

Signature:

9.