

## MAGNETIC PARTICLE INSPECTION REPORT

Date of Inspection: 04.02.2026	Report number: AT6733.26.02.10	Job no: 6733
Name and Address of owner for whom the thorough examination was made:  TRUCK OMAN SULTANATE OF OMAN		Address of premises at which the examination was made:  HAIMA
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box):  <input type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others [TOP SURFACE ONLY]		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7, ASTM E709, AWS D1.1	
Description and identification of the equipment:  <u>FIFTH WHEEL</u>  Make: JOST Type: JSK 38 C Serial No.: 10488223 Reg. No.: 3706 HA Owner ID No.: PLM 1028  Qty: 1no.  Date of Last MPI/ Cert No (If any): 07/07/2025 (VG/4230/25/07/10)		
Result of the above test:  <b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</b>		
Inspected by, Name & Signature: Anoop Thankachan		Latest date by which next MPI must be carried out: 03.08.2026
Qualification: ASNT L2		
Name and address of employer of persons making and authenticating this report:  <b>Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a></b>		