



الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م

SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



MAGNETIC PARTICLE INSPECTION REPORT

| | | |
|--|---|--|
| Date of Inspection: 29.12.2025 | Report number: AT6710.25.12.54 | Job no: 6710 |
| Name and Address of the Owner of the Equipment TRUCK OMAN SULTANATE OF OMAN | Address of premises at which the examination was made: HAIMA | |
| Method: WET Surface Condition: Acceptable | Material: Carbon Steel Equipment: Permanent magnet Yoke | Test temperature: Ambient |
| Area Inspected (tick the appropriate box): <input type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others [TOP SURFACE ONLY] | | |
| WHITE CONTRAST PAINT: Magnavis WCP | MAGNETISING METHOD: Wet suspension black ink | |
| BLACK MAGNETIC INK: Magnaflux 7HF | ACCEPTANCE CODE: ASME V ARTICLE 7, ASTM E709, AWS D1.1 | |
| Description and identification of the equipment: FIFTH WHEEL Make: JOST Type: JSK38C Serial no: 2263491932 Reg no: 918 YB Owner id no: TO 2020 Qty: 1nos Date of Last MPI/ Cert No (If any): 11.07.2025 (AT4482.25.07.56) | | |
| Result of the above test: MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION | | |
| Inspected by Name & Signature: Anoop Thankachan | | Latest date by which next MPI must be carried out: 28.06.2026 |
| Qualification: ASNT L2 | | |
| Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288, Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com | | |