



MAGNETIC PARTICLE INSPECTION REPORT

Date of Through Examination: 17/02/2020	Report number: MP/42136/20/02/144	Job no: 42136
Name and Address of owner for whom the thorough examination was made: TRUCK OMAN SULTANATE OF OMAN	Address of premises at which the examination was made: NIMR	
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): ☐ Weldment areas ☐ Stress Areas ☒ Full Body ☒ Others (TOP PLATE)		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment: <u>FIFTH WHEEL</u> Make : JOST Size : 3½" Fleet No. : PLM 604 Reg. No. : 7208 MA Qty: 1no. Date of Last MPI/ Cert No(If any): 10/03/2019 MP/39039/19/03/161		
Details of tools/equipments used: Magnet (STS-LD-68)		
Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		

Inspected by, Name & Signature : Qualification : ASNT L2	Madhu Pillai 	Latest date by which next MPI must be carried out: 16/02/2021
Name and address of employer of persons making and authenticating this report: SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. lifting@safetyoman.com		



الشركة الفنية لخدمات السلامة ش.م.م
SAFETY *technical* SERVICES CO. LTD.



MAGNETIC PARTICLE INSPECTION REPORT