الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م
SAFETY TECHNICAL SERVICES AND INSPECTIONS
Tel :+968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.

LEEA Full Member

MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 11/08/2020	Report number: O/44464/20/08/01	Job no: 44464

Name and Address of owner for whom the thorough examination was made:	Address of premises at which the examination was made:
TRUCK OMAN RENTAL SULTANATE OF OMAN	JIFFNAIN

Method: WET **Material: Carbon Steel** **Test temperature: Ambient**
Surface Condition: Acceptable **Equipment: Permanent magnet Yoke**

Area Inspected (tick the appropriate box):

☐ Weldment areas ☐ Stress Areas ☐ Full Body ☑ Others [TOP SURFACE]

WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1

Description and identification of the equipment:

FIFTH WHEEL

MAKE: JOST

TYPE: JSK 38C

SERIAL NO: 1483488516

OWNER ID: TO 2003

REG NO: 2908 MR

Qty: 1 no

Date of Last MPI/ Cert No(If any): N/A

Result of the above test :

MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION

Inspected by, Name & Signature : Koshy Mathew Qualification : ASNT L2	Koshy	Latest date by which next MPI must be carried out: 10/08/2021

Name and address of employer of persons making and authenticating this report:

Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS
P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman.
lifting@safetyoman.com

SAFETY TECHNICAL SERVICES & INSPECTIONS LLC CERTIFIED