

MAGNETIC PARTICLE INSPECTION REPORT

| | | |
|---|--|---|
| Date of Thorough Examination: 03/09/2020 | Report number: MP/44427/20/09/01 | Job no: 44427 |
| Name and Address of the Owner of the Equipment TRUCK OMAN EQUIPMENT RENTAL SULTANATE OF OMAN | | Address of premises at which the examination was made: FAHUD # 872 |
| Method: WET Surface Condition: Acceptable | Material: Carbon Steel Equipment: Permanent magnet Yoke | Test temperature: Ambient |
| Area Inspected (tick the appropriate box): <input type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input checked="" type="checkbox"/> Full Body <input type="checkbox"/> Others | | |
| WHITE CONTRAST PAINT: Magnavis WCP | MAGNETISING METHOD: Wet suspension black ink | |
| BLACK MAGNETIC INK: Magnaflux 7HF | ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1 | |
| Description and identification of the equipment: <u>MOBILE CRANE MAIN HOOK MPI</u> | | |
| MAKE OF CRANE: GROVE OWNERS ID NO: PLM 1485 REG NO: 6236 YR HOOK ID: 3502 | | |
| Qty: 1 no | | |
| Date of Last MPI/ Cert No(If any): N/A | | |
| Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION | | |

| | | |
|--|---|---|
| Inspected by, Name & Signature : Koshy Mathew Qualification : ASNT L2 |  | Latest date by which next MPI must be carried out: 02/09/2021 |
| Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com | |  |

