



**CERTIFICATE OF TEST ANDTHOROUGH EXAMINATION OF MOBILE CRANE**

**Certificate No: MA/39313/19/01/01**

**Date of Inspection: 17/01/2019**

Name and Address of the Owner:	<b>PREMIER LOGISTICS MUSCAT</b>
Maker & Date of Manufacture:	GROVE ; 2012
Place of Inspection:	DALMA RIG#72, FAHUD
Ref. Standard:	<b>BS 7121-2-3; PR 1708</b>
Registration No.& Owner No.:	6236 YR ; PLM-1485
Model and Serial No.:	RT 530 E-2 ; 258501
Nr. of running hours and/or km read out:	204212 hours
Manufacturer's documentation:	OK
Date of Previous inspection / cert. no:	29/1/2018 ; RA/36429
Date of Next inspection :	16/01/2020
Date of Previous load test/ cert. no:	9/2/2016 ; A/31551/16/02/1
Date of Next load test:	8/2/2020
Availability of operations manual in cab:	OK
Load Chart in cab:	OK
Accessories certificates:	OK
Availability of daily check report:	OK
Maintenance records / major repairs carried out:	OK

Description of Crane: **Diesel powered, Hydraulically operated, telescopic boom rough terrain crane**

Max.capacity of crane 30 tonnes at 8.8m boom length and 3m radius and using 16mm steel wire rope at 6falls.

**Test carried out according to tabulated column**

<b>Description of test: (configuration of the crane at the time of inspection)</b>	<b>Boom length</b>	<b>Radius</b>	<b>Test load</b>	<b>Safe working load</b>
	(m)	(m)	Tonnes	Tonnes
No. of falls: 6				
Main hook block S.N: 3502	12.2	4	---	21.025 t
Main hook capacity: 30 t				
Wire rope certificate no: 191416006002	15.2	8	---	10.5 t
Hook Cert. no.: 52358	24.4	14	---	4.610 t
	29	26	1.16 t	1.16 t

**Conclusion: Fit for its intended use at the time of inspection.**

Annexure of certificate of test & thorough examination of mobile crane

**Certificate No: MA/39313/19/01/01**

**Date of Inspection: 17/01/2019**

Description	Condition	Remarks
Safe load indicator/calibration verified	Satisfactory	
Level indicator / Angle indicator	Satisfactory	
Telescopic boom extensions/Boompads/Rope guides	Satisfactory	
Lattice boom sections/Connecting pins/Boom back stops	N/A	
Pendant ropes	N/A	
Fly Jib / Luffing jib/ Derricking interlocksecurity	N/F	not stowed
Main hoist winch/ Hoist drum / Correct spooling	Satisfactory	
Main hoist wire ropes and termination	Satisfactory	
Auxiliary hoist winch/ Hoist drum / Correct spooling	N/A	
Auxiliary wire ropes and termination	N/A	
Counterweight and its locking mechanism	Satisfactory	
Access ladders/Walkways/Hand & guard rails	Satisfactory	
Outriggers/ beams / jacks / pads	Satisfactory	
Tires / rims / wheel bolts	Satisfactory	
Crawler Tracks/Track shoe	N/A	
Swing machinery /Swing alarm / Swing lock	Satisfactory	
Swingbearing/ -wear / report	N/A	wear report n/a for verification
Hook block system/Safety catch	Satisfactory	
Hook MPI, certificate no (Required every 4 yrs)	Satisfactory	
Sheaves(Boom & Hook)	Satisfactory	
Operator cab/ Control levers /Wind shields/Mirrors	Satisfactory	
Anti 2 block /over lower/ boom cut off /over load cut off limit switches / Slack rope limiter(if fitted)	Satisfactory	
Proximity switches	N/A	
All fasteners /Bolts / Safety pins	Satisfactory	
Electrical System	Satisfactory	
Hydraulic System	Satisfactory	
Caution rotary light	Satisfactory	
Reverse Horn / Light	Satisfactory	
Fire extinguisher	Satisfactory	
Anemometer(if fitted or hand held)	N/A	
General condition (structural integrity/functionality)	Satisfactory	
Display marking (SWL/tyre pressure/ insp.date/due date)	Satisfactory	

General comments: Nil

Approved by, Name & Signature: Gishin Thomas



Inspected by, Name & Signature: Infano Oswin


