



الشركة الفنية لخدمات السلامة ش.م.م  
**SAFETY *technical* SERVICES CO. LTD.**



**MAGNETIC PARTICLE INSPECTION REPORT**

Date of Thorough Examination: 28/08/2019	Report number: MA/41403/19/08/02	Job no: 41403
Name and Address of owner for whom the thorough examination was made: <b>TRUCK OMAN EQUIPMENT RENTAL SULTANATE OF OMAN</b>		Address of premises at which the examination was made: <b>JIFFNAIN</b>
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box): <input type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input checked="" type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment: <b><u>MPI OF MAIN HOOK OF CRANE</u></b>		
Main hook Serial no. : 10804 Crane Reg. no. : 8332 HA Crane Owner ID No. : PLM 1498		
Result of the above test : <b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONSAT THE TIME OF INSPECTION</b>		
Inspected by, Name & Signature : Qualification : ASNT L2	Malik Mohammed 	Latest date by which next MPI must be carried out: 27/08/2020
Name and address of employer of persons making and authenticating this report: <b>SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a></b>		