



MAGNETIC PARTICLE INSPECTION REPORT

Date of Through Examination: 02/04/2018	Report number: O/37007/18/04/02	Job no: 37007
Name and Address of the Owner of the Equipment PREMIER LOGISTICS MUSCAT LLC SULTANATE OF OMAN		Address of premises at which the examination was made: AL HUWAISHA
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input checked="" type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment: <u>MAIN HOOK OF A ROUGH TERRAIN CRANE</u> <u>Crane Details:</u> Make : Grove ; 2012 Model no. : RT 530E-2 Serial no. : 253577 Reg. No. : 6228 YR Owner ID no. : PLM-1482 <u>Hook Details:</u> SWL : 30 t Hook Cert. No.: 57792 Date of Last MPI / Cert. No. (if any) : 03/04/2017 ; RA/34220/17/04/02		
Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		
Inspected by, Name & Signature : Qualification : ASNT L2	Infanso Oswin 	Latest date by which next MPI must be carried out: 01/04/2019
Name and address of employer of persons making and authenticating this report: SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. lifting@safetyoman.com		