



الشركة الفنية لخدمات السلامة ش.م.م  
SAFETY *technical* SERVICES CO. LTD.



MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 6/03/2020	Report number: V/42370/20/03/05	Job no: 42370
Name and Address of owner for whom the thorough examination was made:  TRUCK OMAN EQUIPMENT RENTAL SULTANATE OF OMAN	Address of premises at which the examination was made:  SAFAH	
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input checked="" type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:  <u>MAIN HOOK OF A ROUGH TERRAIN CRANE</u>		
<u>Crane Details:</u>  Make : Grove ; 2012 Model no. : RT 530E-2 Serial no. : 253577 Reg. No. : 6228 YR Owner ID no. : PLM-1482		
<u>Hook Details:</u>  SWL : 30 t Hook Cert. No.: 57792		
Date of Last MPI / Cert. No. (if any) :17/03/19 MA/39822/19/03/07		
<u>Result of the above test :</u>  <b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONSAT THE TIME OF INSPECTION</b>		

Inspected by, Name & Signature :  Qualification : ASNT L2	Malik Mohammed 	Latest date by which next MPI must be carried out:  After One Year As Per Client Requirement Or At The Discretion Of Lifting Inspector
Name and address of employer of persons making and authenticating this report:  SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		



## MAGNETIC PARTICLE INSPECTION REPORT