



الشركة الفنية لخدمات السلامة ش.م.م  
**SAFETY technical SERVICES CO. LTD.**



**CERTIFICATE OF TEST AND THOROUGH EXAMINATION OF MOBILE CRANE**

Certificate No: O/37007/18/04/01

Date of Inspection: 02/04/2018

Name and Address of the Owner:	PREMIER LOGISTICS MUSCAT			
Maker & Date of Manufacture:	GROVE MANITOWOC ; 2012			
Place of Inspection:	ALHUWAISHA			
Ref. Standard:	BS 7121-2-3; PR 1708			
Registration No.& Owner No.:	6228 YR ; PLM 1482			
Model and Serial No.:	RT 530E-2 ; 258577			
Nr. of running hours and/or km read out:	19620.6 hrs.			
Manufacturer's documentation:	OK			
Date of Previous inspection / cert. no:	03/04/2017 ; RA/34220/17/04/01			
Date of Next inspection :	01/04/2019			
Date of Previous load test/ cert. no:	09/04/2016 ; TCW4026/1/2016			
Date of Next load test:	08/04/2020			
Availability of operations manual in cab:	OK			
Load Chart in cab:	OK			
Accessories certificates:	OK			
Availability of daily check report:	OK			
Maintenance records / major repairs carried out:	OK			
Description of Crane: Diesel powered, Hydraulically operated, telescopic boom rough terrain mobile crane . Max.capacity of crane 30 tonnes at 8.8m boom length and 3m radius and using 16mm steel wire rope at 6falls.				
<b>Test carried out according to tabulated column</b>				
<b>Description of test: (configuration of the crane at the time of inspection)</b>	Boom length	Radius	Test load	Safe working load
No. of falls: 6	(m)	(m)	Tonnes	Tonnes
Main hook Cert. no. : 57792	8.8m	3m	---	30 t
Main hook capacity: 35 t	18.3m	12m	---	6.06 t
Wire rope certificate no: 201309WRM00053 (41)	24.2m	14m	4.6 t	4.6 t
	29m	16m	---	3.42 t
<b>Conclusion: Fit for its intended use at the time of inspection.</b>				

# Annexure of certificate of test & thorough examination of mobile crane

Certificate No: O/37007/18/04/01

Date of Inspection: 02/04/2018

Description	Condition	Remarks
Safe load indicator/calibration verified	✓	
Level indicator / Angle indicator	✓	
Telescopic boom extensions/Boompads/Rope guides	✓	
Lattice boom sections/Connecting pins/Boom back stops	N/A	
Pendant ropes	N/A	
Fly Jib / Luffing jib/ Derricking interlocksecurity	N/A	not stowed
Main hoist winch/ Hoist drum / Correct spooling	✓	
Main hoist wire ropes and termination	✓	
Auxiliary hoist winch/ Hoist drum / Correct spooling	N/A	
Auxiliary wire ropes and termination	N/A	
Counterweight and its locking mechanism	✓	
Access ladders/Walkways/Hand & guard rails	✓	
Outriggers/ beams / jacks / pads	✓	
Tires / rims / wheel bolts	✓	
Crawler Tracks/Track shoe	N/A	
Swing machinery /Swing alarm / Swing lock	✓	
Swingbearing/ -wear / report	N/A	Wear report n/a at the time of inspection
Hook block system/Safety catch	✓	
Hook MPI, certificate no (Required every 4 yrs)	✓	02/04/2018 ; O/37007/18/04/02
Sheaves(Boom & Hook)	✓	
Operator cab/ Control levers /Wind shields/Mirrors	✓	
Anti 2 block /over lower/ boom cut off /over load cut off limit switches / Slack rope limiter(if fitted)	✓	
Proximity switches	✓	
All fasteners /Bolts / Safety pins	✓	
Electrical System	✓	
Hydraulic System	✓	
Caution rotary light	✓	
Reverse Horn / Light	✓	
Fire extinguisher	✓	
Anemometer(if fitted or hand held)	N/A	
General condition (structural integrity/functionality)	✓	
Display marking (SWL/tyre pressure/ insp.date/due date)	✓	

General comments: Nil

Approved by, Name &Signature:Gishin Thomas

Inspected by, Name & Signature: Infanso Oswin

