

MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 27/12/2020	Report number: O/44998/20/12/02	Job no: 44998
Name and Address of owner for whom the thorough examination was made: TRUCK OMAN EQUIPMENT RENTAL LLC SULTANATE OF OMAN		Address of premises at which the examination was made: LEKWAIR HOIST 50
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input type="checkbox"/> Weldment areas <input type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input checked="" type="checkbox"/> Others [TOP SURFACE ONLY]		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:		
TEST CARRIED OUT ON MAIN HOOK		
Make : GROVE MANITOWOC		
Serial No. : 076		
Reg. No. : 6267 YR		
Owner Id: PLM 1484		
Qty: 1no.		
Date of Last MPI/ Cert No(If any):N/A		
Result of the above test :		
MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		
Inspected by, Name & Signature : Koshy Mathew Qualification : ASNT L2		Latest date by which next MPI must be carried out: 26/12/2021
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		

