



MAGNETIC PARTICLE INSPECTION REPORT

Date of Through Examination: 03/04/2018	Report number: O/37012/18/04/02	Job no: 37012
Name and Address of the Owner of the Equipment PREMIER LOGISTICS MUSCAT LLC SULTANATE OF OMAN		Address of premises at which the examination was made: SAIHRAWL
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input checked="" type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment: MAIN HOOK OF A UX HOOK OF THE CRANE		
Crane Reg. No. : 4502 YM		
Owner ID No. : TO 2552		
Main Hook ID No. : 13-2388		
Aux Hook ID No. : 12-8912-12-8914		
Qty. : 1no.		
Date of Last MPI / Cert. No. (if any) : 24/05/2015 ; RA/29476/15/05/1		
Result of the above test :		
MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		
Inspected by, Name & Signature : Qualification : ASNT L2	Infanso Oswin 	Latest date by which next MPI must be carried out: 02/04/2019
Name and address of employer of persons making and authenticating this report: SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. lifting@safetyoman.com		