



MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 19/09/2018	Report number: O/38456/18/09/01	Job no: 38456
Name and Address of owner for whom the thorough examination was made:  PREMIER LOGISTICS MUSCAT SULTANATE OF OMAN	Address of premises at which the examination was made:  YIBAL	
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:  <u>FORK UPPER &amp; LOWER HOOKS, HEEL &amp; TOE</u>		
<p>Make : TOYOTA Reg. No. : 2174 BK Owner ID No. : TO 803</p> <p><u>Fork Lift Details :</u> Model No. : FD30 Serial no. : 31214</p> <p>Qty: 1pair</p> <p>Date of Last MPI/ Cert No( If any): N/A</p> <p><b>Result of the above test :</b></p> <p><b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</b></p>		
Inspected by, Name & Signature :  Qualification : ASNT L2	Infanso Oswin 	Latest date by which next MPI must be carried out:  18/09/2019
Name and address of employer of persons making and authenticating this report:  SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		