



**TA'AZEEZ ENTERPRISES LLC**Po Box: 23, Pc: 103-AL Qurum North AL Ghoubra- Bowsheer  
Sultanate Of Oman**MAGNETIC PARTICLE INSPECTION REPORT**

Company Name and Address TRUCK OMAN NORTH LLC		Inspection Location: JIFFNAIN
Certificate Number: KM.3301.03.26.02.02		Job No: 03301
Date of Thorough Examination: 02-03-2026	Time of Inspection: 10:40	Issue Date: 02-03-2026
Date of Previous MPI/ cert no: AT/5184/25/09/05		Date of Next Examination: After One Year As Per Clients Requirements Or At The Discretion Of Inspector
Description: FORK MPI		
Description and identification of the equipment:  REG NO: 701 YS OWNER ID: TER-1526		
Area Inspected ( tick the appropriate box): <input type="checkbox"/> weldment area <input checked="" type="checkbox"/> Stress Area <input checked="" type="checkbox"/> Full Body <input type="checkbox"/> Others (top surface)		
WHITE CONTRAST PAINT: ZCHEK WP	MAGNETISING METHOD: WET SUSPENSION BLACK INK	
BLACK MAGNETIC INK: ZCHEK 9E Black	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
TEST METHOD: WET	MATERIAL: CARBON STEEL	
TEST TEMPERATURE: AMBIENT	SURFACE CONDITION: ACCEPTABLE	
TEST EQUIPMENT: PERMANENT MAGNET YOKE		
Result of the above test: MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		

Inspected by: KAZIM MOHSIN Qualifications: ASNT LEVEL II   Signature: Date: 02-03-2026	Company Stamp 
--	---

If any Alteration/Major Repair is made, this certificate is rendered invalid.  
This is to confirm that the item listed above was examined by the undersigned competent representative in compliance with the aforementioned standard. The aforementioned objects were found to be free of faults, deformations, and other problems at the time of inspection. The equipment is suitable for its intended use within the permitted limits, and at the time of inspection, it was determined to be suitable for continued use, provided that continuous maintenance is applied, qualified operators are employed, and our comments and recommendations are put into practice.

The inspection certificate may not be republished in its entirety without the consent of the inspection body and the customer. Inspection is confined to the work ordered or lots inspected. Contact us at <a href="mailto:info@tis-om.com">info@tis-om.com</a> for certificate authenticity and clarification or scan QR code.	
---	---