




الشركة الفنية لخدمات السلامة ش.م.م
SAFETY *technical* SERVICES CO. LTD.



MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 05/04/2018	Report number: G/36878/18/04/04	Job no: 36878
Name and Address of owner for whom the thorough examination was made: PREMIER LOGISTICS SULTANATE OF OMAN	Address of premises at which the examination was made: YIBAL	
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment: <u>FORK MPI ON HEEL AND MAST HOLDING BRACKET</u>		
Owner ID No. : PLM - 1521		
Make : CATERPILLAR		
Forklift Reg. No. : 1549 ML		
Fork Dimension: 1200 x 120 x 770mm (LxWxH)		
Qty: 1no		
Date of Last MPI/ Cert No(If any): 25/10/2017 ; MP/35901/17/10/08		
Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONSAT THE TIME OF INSPECTION		
Inspected by, Name & Signature : Qualification : ASNT L2	George Joju 	Latest date by which next MPI must be carried out: 04/04/2019
Name and address of employer of persons making and authenticating this report: SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. lifting@safetyoman.com		