



الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م. SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



CERTIFICATE OF THOROUGH EXAMINATION AND TEST

Certificate No: A/45901/21/02/02

Date of Inspection: 10/02/2021

Name and Address of the Owner:	PREMIER LOGISTICS
Maker & Date of Manufacture:	CATERPILLAR ; 2011
Place of Inspection:	FARAH
Ref. Standard:	BS EN 474-3; BS ISO 2330 SP2275
Registration No. & Owner No.:	4844 MR ; PLM-1522
Model No. and Serial No.:	930H ; CAT0930HEDHC03391
Running hours:	16769 hrs.
Manufacturer's documentation:	In Services Equipment
Date of Previous inspection / cert no:	28/08/2020; (O/44483/20/08/17)
Date of Next inspection:	09/08/2021
Date of Previous load test / cert no:	28/08/2020; (O/44483/20/08/17)
Date of Next load test:	27/08/2024
Availability of operations manual in cabin:	Satisfactory
Availability of daily check report:	Satisfactory

Description of Forklift:
Diesel powered hydraulically operated articulated Wheel Loader c/w fork SWL: 5000 kgs @ 600 mm load center.

Test carried out according to tabulated column

Description of test:	Test load applied In kgs	S.W.L In kgs
Functional test carried out.		
Max. Lifting Height: 3889 mm		
Hydraulic creep : Nil		
Fork Serial No: 713-C370 (Pair)	----	5000 Kg

Conclusion: Fit for its intended use at the time of inspection. / Refer to checklist- Annexure of certificate

This certificate becomes invalid if any Alteration/Major Repair and modification is done.

This is to certify that the undersigned competent representative, did attend to examine the item described above in accordance to the aforementioned standard. At the time of inspection, the said item were found to be free from flaws, deformations or other defects. The equipment is satisfactory for its intended use within the limits specified and at the time of inspection was found to be satisfactory for further use, provided there is continuous maintenance applied, qualified operators employed and implementation of our remarks and recommendations.

Approved by, Name & Signature: Gishin Thomas

Inspected by, Name & Signature: Mohammed Anaz





الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م

SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



Annexure of certificate of test & thorough examination

Certificate No: A/45901/21/02/02

Date of Inspection: 09/02/2021

Status Legend: S- Satisfactory NA-Not applicable F-Findings CF-Critical Findings					
No.	Description	Status	No.	Description	Status
1	Operations Manual/Catalogue	NA	17	All gauges in cab	S
2	Monthly Inspection record	NA	18	Overhead & foot guard	S
3	Maintenance records	NA	19	Exhaust system	S
4	OEM Specification plate	S	20	Side shifting function (if applicable)	NA
5	Tires, rims, wheel bolts and axles	S	21	Horn, reverse alarm, rotating warning light	S
6	Masts and Back rest , carriage	S	22	Lights & indicators	F
7	Forks and its extensions, slide end stopper, locks	S	23	Seat and seat belts	S
8	Load chain and its assemblies	S	24	Parking brake and foot brake function	S
9	Side rollers and roll over cage	S	25	Fire extinguisher	S
10	Safety devices	S	26	Display markings (SWL, tire pressure, insp. date, due date)	S
11	Battery and its connections	S	27	Full functional test	S
12	Hydraulic system & hoses and end fittings	S	28	Rated load test	NA
13	Electrical system & Cables	S	29	Overload test	NA
14	Cooling system	S	30	NDT(If applicable)	NA
15	Steering function	S	31	Other Test (If applicable)	NA
16	All controls levers function & symbols legible	S	32	General Condition	S
Details of tools/equipments used: STS-LD-78, STS-LD-77					
Findings/Critical Findings Report					
F/CF	No.	Remarks			
F	30	Fork MPI Done On (10/02/2021; A/45901)			
F	5	Recommended To Change Rear Right Side Tyre (ASAP)			

