

CERTIFICATE OF TEST & THOROUGH EXAMINATION OF A FORKLIFT
IN-SERVICE INSPECTION

Ident/Cert. No.: RK/FEB22/099 **Our Ref. No.:** RK 1165 **Date of inspection :** 09/02/2022
Date of issue : 11/02/2022

Name and Address of the Owner:	Truck Oman LLC.
Maker & Date of Manufacture:	Caterpillar, 2012
Place of Inspection:	Lekhwaier, H-50
Internationally accepted Ref. Standard	BS EN 1459-1:2017+A1:2020, BS EN ISO 3691-1:2015+A1:2020 ISO 22915-2:2018
Specification of Regional Regulatory Authority	PDO SP-2275:2021
Registration No. & Owner No.:	Reg. No.: 4043 YM & Owner No.: PLM 1529
Model No. and Serial No.:	Model no.: 930 H & Serial no.: CAT0930HHDHC04118
Running hours:	22462 hrs
Manufacturer's documentation:	Available
Date of Previous Inspection / cert no:	07/10/2021 & Cert. No.: VK/OCT21/009 (OTIS)
Date of Inspection:	09/02/2022
Date of Next Inspection:	08/08/2022
Date of load test:	07/10/2021
Date of Next load test:	06/10/2022
Availability of operations manual in cabin:	Available
Availability of daily check report:	To be placed in cabin
Description of Forklift: Diesel powered hydraulic Articulated forklift SWL : 5,000 kg @ 500mm load center Maximum Height of lift: 4049 mm	

Description of test:	Test load applied	S.W.L
	In kgs	In kgs
Performance test, Visual Inspection & fully functional test carried out as per tabulated column Load cell used: Yes	5,000	5,000
Hydraulic creep : Nil		

Conclusion: Fit for its intended use

Approved by GM/OM/TM,

Name & signature: Jahan Pourjahangiri

OTIS/CERT/FLT/01




Rev no. 02

Rev Date: 07.01.2021

Inspected by,

Name & signature: Rishad K A

for 

Page 1 of 2

Annexure of Certificate of Test & Thorough Examination of a Forklift

Ident/Cert. No.: RK/FEB22/099

Our Ref. No. : RK 1165

Date of inspection : 09/02/2022

Date of issue : 11/02/2022

Description	Condition	Remarks
Tires, rims, wheel bolts and axles	✓	
Masts and Back rest , carriage	✓	
Forks and its extensions, slide end stopper, locks	✓	
Wear & Shank angle	✓	
Load chain and its assemblies	X	Not Applicable
Side rollers and roll over cage	✓	
Safety devices	✓	
Battery and its connections	✓	
Hydraulic system & hoses and end fittings	✓	
Electrical system & Cables	✓	
Cooling system	✓	
Steering function	✓	
All controls levers function & symbols legible	✓	
Capacity plate in place and legible	✓	
All gauges in cab	✓	
Overhead & foot guard	✓	
Exhaust system	✓	
Side shifting function (if applicable)	X	Not Fitted
Horn, reverse alarm, rotating warning light	✓	
Lights & indicators	✓	
Seat and seat belts	✓	
Parking brake and foot brake function	✓	
Fire extinguisher	✓	
MPI fork blades, date / report nbr. (annually)	✓	Cert.no.: KJ/SEP21/090 valid until 13/09/2022
Mast disassembly (every 4 years)	✓	
General condition	✓	
Display markings (SWL, tire pressure, insp. date, due date)	✓	

General comments: All the Conditions mentioned above found, at the time of Inspection.

Fit for its intended use

Approved by GM/OM/TM,

Inspected by,

Name & signature: Jahan Pourjahanigiri

Name & signature: Rishad K A

OTIS/CERT/FLT/01



Rev Date: 07.01.2021

Page 2 of 2