



MAGNETIC PARTICLE INSPECTION REPORT

Date of Through Examination: 07/05/2019	Report number: O/40334/19/05/04	Job no: 40334
Name and Address of owner for whom the thorough examination was made: TRUCK OMAN EQUIPMENT RENTAL SULTANATE OF OMAN		Address of premises at which the examination was made: KHAZZAN
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7, ASTM E709, AWS D1.1	
Description and identification of the equipment: Test Carried Out On Fork, Heel ; Toe & Upper, Lower hooks weldings.		
Forklift details Make : Caterpillar Owner id: PLM 1523 Registration no: 4870 MR		
Fork details Fork id: 2 & 50		
Qty: 1 pair		
Date of Last MPI/ Cert No(If any): 23/05/2018 ; MA/37565/18/05/03		
Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONSAT THE TIME OF INSPECTION		
Inspected by, Name & Signature : Qualification : ASNT L2	Infanso Oswin 	Latest date by which next MPI must be carried out: 06/05/2020
Name and address of employer of persons making and authenticating this report: SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. lifting@safetyoman.com		



REPORT OF THOROUGH EXAMINATION & TEST

Date of Thorough Examination: 30/10/2019	Report number: A/41814/19/10/06	Job no: 41814
---	------------------------------------	------------------

Name and Address of the Owner of the Equipment TRUCK OMAN EQUIPMENT RENTAL SULTANATE OF OMAN		Address of premises at which the examination was made: UWAISIYA (H51)	
Description and identification of the equipment: MATERIAL HANDLING STINGER		Test Load	S.W.L
Make : CATERPILLAR		---	2.333 t @ 1 st boom
Serial no. : 229-9714		---	1.86 t @ 2 nd boom
Owner ID No. : PLM-1523		---	1.55 t @ 3 rd boom
Date of Previous Examination/ cert no: 07/05/2019 ; O/40334/19/05/03	Date of Next Examination: 29/04/2020		
Date of previous Load test/ Cert no: 07/05/2019 ; O/40334/19/05/03	Date of Next Load test: 06/05/2023		
Ref. Standards: ISO 13284 ; SP 2275			
Comments (If any): NONE			
Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE			
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none state NONE) NONE			
IS THIS EQUIPMENT FIT FOR PURPOSE?		YES	<input checked="" type="checkbox"/>

Inspected by, Name & Signature: Mohammed Anaz 	Approved by, Name & Signature Gishin Thomas 	
Name and address of employer of persons making and authenticating this report: SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. lifting@safetyoman.com		



REPORT OF THOROUGH EXAMINATION & TEST

Date of Thorough Examination: 30/10/2019	Report number: A/41814/19/10/07	Job no: 41814
---	------------------------------------	------------------

Name and Address of the Owner of the Equipment TRUCK OMAN EQUIPMENT RENTAL SULTANATE OF OMAN	Address of premises at which the examination was made: UWAISIYA (H51)
Description and identification of the equipment: <u>WHEEL LOADER BUCKET</u>	
Make : CATERPILLAR	
Fleet No. : PLM-1523	
Bucket Serial no. : 25154	
Bucket Capacity : 2.8m ³	
Date of Previous Examination/ cert no: 07/05/2019 ; O/40334/19/05/02	Date of Next Examination: 29/04/2020
Ref. Standards: BS EN 474-3 ; SP 2275	
Comments(if any): NONE	
Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE	
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:(If none state NONE) NONE	

IS THIS EQUIPMENT FIT FOR PURPOSE?	YES	<input checked="" type="checkbox"/>	NO	
------------------------------------	-----	-------------------------------------	----	--

Inspected by, Name & Signature: Mohammed Anaz 	Approved by, Name & Signature Gishin Thomas 	
Name and address of employer of persons making and authenticating this report: SAFETY TECHNICAL SERVICES PO BOX 3288, SEEB, PC 111 MUSCAT. lifting@safetyoman.com		