



MAGNETIC PARTICLE INSPECTION REPORT

Date of Through Examination: 07/05/2019	Report number: O/40334/19/05/04	Job no: 40334
Name and Address of owner for whom the thorough examination was made: TRUCK OMAN EQUIPMENT RENTAL SULTANATE OF OMAN		Address of premises at which the examination was made: KHAZZAN
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment: <u>Test Carried Out On Fork, Heel ; Toe & Upper, Lower hooks weldings.</u>		
<u>Forklift details</u> Make : Caterpillar Owner id: PLM 1523 Registration no: 4870 MR		
<u>Fork details</u> Fork id: 2 & 50		
Qty: 1 pair		
Date of Last MPI/ Cert No(If any): 23/05/2018 ; MA/37565/18/05/03		
Result of the above test :		
MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONSAT THE TIME OF INSPECTION		

Inspected by, Name & Signature : Qualification : ASNT L2		Latest date by which next MPI must be carried out: 06/05/2020
Name and address of employer of persons making and authenticating this report: SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. lifting@safetyoman.com		