

MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 29/04/2020	Report number: A/43476/20/04/02	Job no: 43476
Name and Address of owner for whom the thorough examination was made: TRUCK OMAN EQUIPMENT RENTAL SULTANATE OF OMAN		Address of premises at which the examination was made: T58-SAHMA
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	

Description and identification of the equipment:

Test Carried Out On Fork, Heel; Upper & Lower hooks welding's.

Forklift details

Make : Caterpillar
Owner id: PLM 1523
Registration no: 4870 MR

Fork details

Fork Serial : 2390047-L8 & 2328584-L8

Qty: 1 pair

Date of Last MPI/ Cert No(If any): 07/05/19 (O/40334)

Result of the above test :

MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION

Inspected by, Name & Signature : Koshy Mathew		Latest date by which next MPI must be carried out: 28/04/2021
Qualification : ASNT L2		
Name and address of employer of persons making and authenticating this report: Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. lifting@safetyoman.com		

