



### CERTIFICATE OF TEST AND THOROUGH EXAMINATION

Certificate No: MP/39002/18/11/01

Date of Inspection: 30/11/2018

Name and Address of the Owner:	PREMIER LOGISTICS	
Maker & Date of Manufacture:	CATERPILLAR ; 2011	
Place of Inspection:	YIBAL (# 50)	
Ref. Standard:	ISO22915-2 /BS EN 1459/SP 2275	
Registration No. & Owner No.:	4870 MR ; PLM-1523	
Model No. and Serial No.:	930H ; CAT0930HCDHC03392	
Running hours:	25115 HRS.	
Manufacturer's documentation:	YES	
Date of Previous inspection / cert no:	22/05/2018 ; O/37518/18/05/01	
Date of Next inspection:	29/05/2019	
Date of Previous load test / cert no:	23/12/2015 ; O/30791/15/12/01	
Date of Next load test:	22/12/2019	
Availability of operations manual in cabin:	YES	
Availability of daily check report:	YES	
Description : Diesel powered hydraulic articulated wheel loader SWL : 5000kgs @ 600mm load center,		
<b>Test carried out according to tabulated column</b>		
Description of test:	Test load applied In kgs	S.W.L In kgs
	Functional test carried out found satisfactory  Max. Lifting Height: 4049mm  Hydraulic creep : Nil	5000 kg
<b>Conclusion: Fit for its intended use at the time of inspection.</b>		

Approved by, Name & Signature: Gishin Thomas

Inspected by, Name & Signature : Madhu Pillai



## Annexure of certificate of test & thorough examination

Certificate no: MP/39002/18/11/01

Inspection date: 30/11/2018

Description	Condition	Remarks
Tires, rims, wheel bolts and axles	Satisfactory	
Masts and Back rest , carriage	Satisfactory	
Forks and its extensions, slide end stopper, locks	Satisfactory	
Load chain and its assemblies	N/A	
Side rollers and roll over cage	N/A	
Safety devices	N/A	
Battery and its connections	Satisfactory	
Hydraulic system & hoses and end fittings	Satisfactory	
Electrical system & Cables	Satisfactory	
Cooling system	Satisfactory	
Steering function	Satisfactory	
All controls levers function & symbols legible	Satisfactory	
Capacity plate in place and legible	Satisfactory	
All gauges in cab	Satisfactory	
Over head & foot guard	Satisfactory	
Exhaust system	Satisfactory	
Side shifting function (if applicable)	N/A	
Horn, reverse alarm, rotating warning light	Satisfactory	
Lights & indicators	Satisfactory	
Seat and seat belts	Satisfactory	
Parking brake and foot brake function	Satisfactory	
Fire extinguisher	Satisfactory	
MPI fork blades, date / report nr. (annually)	Satisfactory	Due on : 22/05/2019 ; MA/37565/18/05/03
Mast disassembly (every 4 years)	N/A	
General condition	Satisfactory	
Display markings (SWL, tire pressure, insp. date, due date)	Satisfactory	

General comments: Nil

Approved by, Name & Signature: Gishin Thomas

Inspected by, Name & Signature : Madhu Pillai



