



الشركة الفنية لخدمات السلامة ش.م.م  
SAFETY *technical* SERVICES CO. LTD.



MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 26/12/2019	Report number: A/41838/19/12/01	Job no: 41838
Name and Address of owner for whom the thorough examination was made:  PREMIER LOGISTICS MUSCAT SULTANATE OF OMAN	Address of premises at which the examination was made:  SAIH RAWL (H-52)	
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:  <b>FORK MPI</b>  FORK S\N- 1945591-L8 (PAIR)  OWNER ID # PLM - 1530  Qty: 1no		
Date of Last MPI/ Cert No( If any): 17/1/19/(MA/39312/19/01/03)		
Result of the above test :  <b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONSAT THE TIME OF INSPECTION</b>		
Inspected by, Name & Signature :  Qualification : ASNT L2	MOHAMMAD ANAZ 	Latest date by which next MPI must be carried out:  25/12/2020
Name and address of employer of persons making and authenticating this report:  SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		