



### CERTIFICATE OF TEST AND THOROUGH EXAMINATION OF FORKLIFT

Certificate No: RA/36422/18/01/01

Date of Inspection: 24/01/2018

Name and Address of the Owner:	PREMIER LOGISTICS MUSCAT	
Maker & Date of Manufacture:	CATERPILLAR ; 2015	
Place of Inspection:	YIBAL	
Ref. Standard:	ISO22915-2 /BS EN 1459/PR1708	
Registration No. & Owner No.:	1602 BA ; PLM 1530	
Model No. and Serial No.:	930K ; CAT0930KCEYE00633	
Running hours:	11450 hrs.	
Manufacturer's documentation:	OK	
Date of Previous inspection / cert no:	14/08/2017 ; O/35324/17/08/01	
Date of Next inspection:	23/07/2018	
Date of Previous load test / cert no:	21/8/2016 ; LTC-001 (SOS)	
Date of Next load test:	20/8/2020	
Availability of operations manual in cabin:	OK	
Availability of daily check report:	OK	
Description of Forklift: Diesel powered hydraulically articulated Wheel loader c/w fork SWL: 5000 kg @ 600mm load center.		
<b>Test carried out according to tabulated column</b>		
Description of test: Visual inspection & Performance test  Functional test carried out found satisfactory  Hydraulic creep : Nil  Bucket Serial no. : 141001736 Capacity : 2.7m <sup>3</sup>	Test load applied In kgs	S.W.L In kgs
	<b>5000 kg</b>	<b>5000 kg</b>
<b>Conclusion: Fit for its intended use at the time of inspection.</b>		

Approved by, Name & Signature: Gishin Thomas

Inspected by, Name & Signature: Infanso Oswin



## Annexure of certificate of test & thorough examination of Fork lift

Certificate no: RA/36422/18/01/01

Inspection date: 24/01/2018

Description	Condition	Remarks
Tires, rims, wheel bolts and axles	✓	
Masts and Back rest , carriage	✓	
Forks and its extensions, slide end stopper, locks	✓	
Load chain and its assemblies	N/A	
Side rollers and roll over cage	N/A	
Safety devices	✓	
Battery and its connections	✓	
Hydraulic system & hoses and end fittings	✓	
Electrical system & Cables	✓	
Cooling system	✓	
Steering function	✓	
All controls levers function & symbols legible	✓	
Capacity plate in place and legible	✓	
All gauges in cab	✓	
Over head & foot guard	✓	
Exhaust system	✓	
Side shifting function (if applicable)	N/A	
Horn, reverse alarm, rotating warning light	✓	
Lights & indicators	✓	
Seat and seat belts	✓	
Parking brake and foot brake function	✓	
Fire extinguisher	✓	
MPI fork blades, date / report nr. (annually)	✓	24/01/2018 ; RA/36422/18/01/03
Mast disassembly (every 4 years)	N/A	
General condition	✓	
Display markings (SWL, tire pressure, insp. date, due date)	✓	

General comments: Nil

Approved by, Name & Signature: Gishin Thomas

Inspected by, Name & Signature : Infanso Oswin



