



REPORT OF THOROUGH EXAMINATION & TEST

Date of Thorough Examination: 24/02/2019	Report number: O/39666/19/02/02	Job no: 39666
---	------------------------------------	------------------

Name and Address of the Owner of the Equipment <b>TRUCK OMAN RENTAL LLC SULTANATE OF OMAN</b>		Address of premises at which the examination was made: <b>HINYA</b>	
Description and identification of the equipment:  <b>MATERIAL HANDLING ARM</b>  Make : CATERPILLAR Model No. : 930 H Owner ID No. : TO-2524 Reg. No. : 1002 YD		Test Load	S.W.L
		---	1 <sup>st</sup> boom – 2.33 t
		---	2 <sup>nd</sup> boom – 1.86 t
		3 <sup>rd</sup> boom – 1.3 t	3 <sup>rd</sup> boom – 1.55 t
Date of Previous Examination/ cert no: <b>26/08/2018 ; MA/38255/18/08/04</b>	Date of Next Examination: <b>23/08/2019</b>		
Date of previous Load test/ Cert no: <b>23/01/2014 ; A/26415</b>	Date of Next Load test: <b>28/10/2021</b>		
Ref. Standards: ISO 13284			
Comments (If any): <b>NONE</b>			
Particulars of any repair, renewal or alteration required to remedy the defect identified above: <b>NONE</b>			
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none state NONE)  <b>NONE</b>			
IS THIS EQUIPMENT FIT FOR PURPOSE?		YES	<input checked="" type="checkbox"/>
		NO	

Inspected by, Name & Signature Infando Oswin 	Approved by, Name & Signature Gishin Thomas 	
Name and address of employer of persons making and authenticating this report:  <b>SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a></b>		