



REPORT OF THOROUGH EXAMINATION & TEST

Date of Thorough Examination: 22/08/2019	Report number: O/41272/19/08/02	Job no: 41272
---	------------------------------------	------------------

Name and Address of the Owner of the Equipment TRUCK OMAN RENTAL LLC SULTANATE OF OMAN	Address of premises at which the examination was made: YIBAL	
Description and identification of the equipment: <u>MATERIAL HANDLING ARM</u>	Test Load	S.W.L
Make : CATERPILLAR	1 st boom – 2.5 t	1 st boom – 2.33 t
Model No. : 930 H	---	2 nd boom – 1.86 t
Owner ID No. : TO-2524	3 rd boom – 1.7 t	3 rd boom – 1.55 t
Reg. No. : 1002 YD		

Date of Previous Examination/ cert no: 24/02/2019 ; O/39666/19/02/02	Date of Next Examination: 21/02/2020
Date of previous Load test/ Cert no: 23/01/2014 ; A/26415	Date of Next Load test: 21/08/2023
Ref. Standards: ISO 13284	
Comments(If any): NONE	
Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE	
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:(If none state NONE) NONE	
'S THIS EQUIPMENT FIT FOR PURPOSE?	YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>

Inspected by, Name & Signature Infando Oswin 	Approved by, Name & Signature Gishin Thomas 	
Name and address of employer of persons making and authenticating this report: SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. lifting@safetyoman.com		



الشركة الفنية لخدمات السلامة ش.م.م
SAFETY *technical* SERVICES CO. LTD.



REPORT OF THOROUGH EXAMINATION

Date of Thorough Examination: 22/08/2019	Report number: O/41272/19/08/03	Job no: 41272
---	------------------------------------	------------------

Name and Address of the Owner of the Equipment TRUCK OMAN RENTAL LLC SULTANATE OF OMAN	Address of premises at which the examination was made: YIBAL
--	---

Description and identification of the equipment:

WHEEL LOADER BUCKET

Make : CATERPILLAR

Model No. : 930 H

Owner ID No. : TO-2524

Reg. No. : 1002 YD

Bucket Capacity : 2.3m³

Date of Previous Examination/ cert no: 26/08/2018 ; MA/38255/18/08/05	Date of Next Examination: 21/02/2020
--	---

Ref. Standards: LOLER 98

Comments(if any): **NONE**

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

NONE

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:(If none state NONE)

NONE

IS THIS EQUIPMENT FIT FOR PURPOSE?	YES	<input checked="" type="checkbox"/>	NO	
------------------------------------	-----	-------------------------------------	----	--

Inspected by, Name & Signature Infando Oswin 	Approved by, Name & Signature Gishin Thomas 	
Name and address of employer of persons making and authenticating this report: SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. lifting@safetyoman.com		