



# الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م.

## SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272. Email: [stsi@safetyoman.com](mailto:stsi@safetyoman.com), Website: [www.safetyoman.com](http://www.safetyoman.com)  
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



### CERTIFICATE OF THOROUGH EXAMINATION

Date of Thorough Examination: 02/09/2020	Report number: O/44487/20/09/04	Job no: 44487
---	------------------------------------	------------------

Name and Address of the Owner of the Equipment  TRUCK OMAN RENTAL LLC SULTANATE OF OMAN	Address of premises at which the examination was made:  YIBAL
--	---

Description and identification of the equipment:
--

#### WHEEL LOADER BUCKET

Make : CATERPILLAR

Model No. : 930 H

Owner ID No. : PLM-2524

Reg. No. : 1002 YD

Bucket Capacity : 2.3m<sup>3</sup>

Ref. Standards: LOLER 98

Details of tools/equipment used: STS-VC-7949; STS-LD-63

Date of Previous Examination/ cert no: 18/02/2020; O/42618/20/02/02	Date of Next Examination: 01/03/2021
--	---

Comments(If any): Visual Inspection Carried Out

**RESULT:** The above mentioned equipment was found to be in order for its intended use at the time of inspection.

*This certificate becomes invalid if any Alteration/Major Repair and modification is done.*

This is to certify that the undersigned competent representative, did attend to examine the item described above in accordance to the aforementioned standard. At the time of inspection, the said item were found to be free from flaws, deformations or other defects. The equipment is satisfactory for its intended use within the limits specified and at the time of inspection was found to be satisfactory for further use, provided there is continuous maintenance applied, qualified operators employed and implementation of our remarks and recommendations.

Inspected by, Name & Signature: Infanso Oswin  	Approved by, Name & Signature Gishin Thomas  	
Name and address of employer of persons making and authenticating this report:		
<b>Address:</b> SAFETY TECHNICAL SERVICES AND INSPECTIONS <b>P.O. Box 3288, Airport Heights PC 111 Sultanate of Oman.</b> <b><a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a></b>		





CERTIFICATE OF THOROUGH EXAMINATION & TEST

Date of Thorough Examination: 02/09/2020	Report number: O/44487/20/09/05	Job no: 44487
---	------------------------------------	------------------

Name and Address of the Owner of the Equipment  TRUCK OMAN RENTAL LLC SULTANATE OF OMAN		Address of premises at which the examination was made:  YIBAL	
Description and identification of the equipment:		Test Load	S.W.L
<u>MATERIAL HANDLING ARM</u>  Make : CATERPILLAR  Model No. : 930 H  Owner ID No. : PLM-2524  Reg. No. : 1002 YD		---	1 <sup>st</sup> boom – 2.33 t  ---  2 <sup>nd</sup> boom – 1.86 t  3 <sup>rd</sup> boom – 1.55 t
Ref. Standards: ISO 13284			
Details of tools/equipments used: STS-LD-65; STS-LD-75.			
Date of Previous Examination/ cert no: 18/02/2020; O/42618/20/02/04	Date of Next Examination: 01/03/2021		
Date of previous Load test/ Cert no: 18/02/2020; O/42618/20/02/04	Date of Next Load test: 21/08/2023		
Comments (If any): Rated Load Test Carried Out On 3 <sup>rd</sup> Boom			
<b>RESULT:</b> The above mentioned equipment was found to be in order for its intended use at the time of inspection. <i>This certificate becomes invalid if any Alteration/Major Repair and modification is done.</i> This is to certify that the undersigned competent representative, did attend to examine the item described above in accordance to the aforementioned standard. At the time of inspection, the said item were found to be free from flaws, deformations or other defects. The equipment is satisfactory for its intended use within the limits specified and at the time of inspection was found to be satisfactory for further use, provided there is continuous maintenance applied, qualified operators employed and implementation of our remarks and recommendations.			

Inspected by, Name & Signature: Infando Oswin  	Approved by, Name & Signature Gishin Thomas  	
Name and address of employer of persons making and authenticating this report:  <b>Address:</b> SAFETY TECHNICAL SERVICES AND INSPECTIONS <b>P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman.</b> <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		





## MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 02/09/2020	Report number: O/44487/20/09/06	Job no: 44487
Name and Address of the Owner of the Equipment TRUCK OMAN EQUIPMENT RENTAL SULTANATE OF OMAN		Address of premises at which the examination was made: YIBAL
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:  <b>FORKS HEEL UPPER &amp; LOWER HOOKS</b>  MAKE: CATERPILLAR  FORK LIFT REG NO: 1002 YD  OWNER ID NO: TO 2524  FORK SERIAL NO: 195-6935 ( PAIR )		
Qty: 1 PAIR		
Date of Last MPI/ Cert No( If any): 02/06/19; K/40433/19/06/03		
Result of the above test :  <b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</b>		

Inspected by, Name & Signature : Koshy Mathew		Latest date by which next MPI must be carried out: 01/09/2021
Qualification : ASNT L2		
Name and address of employer of persons making and authenticating this report:  <b>Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a></b>		

