



### CERTIFICATE OF THOROUGH EXAMINATION OF FORKLIFT

Certificate No: MP/34757/17/05/04

Date of Inspection: 21/05/2017

|   |                                |                    |
|---|--------------------------------|--------------------|
| Name and Address of the Owner:  | PREMIER LOGISTICS MUSCAT       |                    |
| Maker & Date of Manufacture:  | CATERPILLAR                    |                    |
| Place of Inspection:  | LR # 10 ; AL HUWAISHA          |                    |
| Ref. Standard:  | ISO22915-2 /BS EN 1459/PR1708  |                    |
| Registration No. & Owner No.:   | 1002 YD ; TO-2524              |                    |
| Model No. and Serial No.:   | 930 H ; CAT0930HADHC04021      |                    |
| Running hours:  | 15520 hrs.                     |                    |
| Manufacturer's documentation:   | Yes                            |                    |
| Date of Previous inspection / cert no:  | 10/12/2016 ; MP/33371/16/12/01 |                    |
| Date of Next inspection:  | 20/11/2017                     |                    |
| Date of Previous load test / cert no:   | 23/01/2014 ; A/26415/14/1/01   |                    |
| Date of Next load test:   | 22/01/2018                     |                    |
| Availability of operations manual in cabin:   | Yes                            |                    |
| Availability of daily check report:   | Yes                            |                    |
| Description of Forklift:<br>Diesel powered hydraulically operated articulated Wheel Loader SWL : 6300kgs @ 600mm load center. |                                |                    |
| <b>Test carried out according to tabulated column</b>   |                                |                    |
| Description of test:  | Test load applied<br>In<br>kgs | S.W.L<br>In<br>kgs |
|   | 6.3 t                          | 6.3 t              |
| Visual inspection, Functional test & Performance test carried out.  |                                |                    |
| Max. Lifting Height: 3889mm   |                                |                    |
| Hydraulic creep : Nil   |                                |                    |
| <b>Conclusion: Fit for its intended use at the time of inspection.</b>  |                                |                    |

Approved by, Name & Signature: Gishin Thomas

Inspected by, Name & Signature: Madhu Pillai



## Annexure of certificate of thorough examination of Fork lift

Certificate no: MP/34757/17/05/04

Inspection date: 21/05/2017

| Description   | Condition | Remarks                              |
|---|-----------|--------------------------------------|
| Tires, rims, wheel bolts and axles                          | ✓         |                                      |
| Masts and Back rest , carriage                              | ✓         |                                      |
| Forks and its extensions, slide end stopper, locks          | ✓         |                                      |
| Load chain and its assemblies                               | N/A       |                                      |
| Side rollers and roll over cage                             | N/A       |                                      |
| Safety devices  | ✓         |                                      |
| Battery and its connections                                 | ✓         |                                      |
| Hydraulic system & hoses and end fittings                   | ✓         |                                      |
| Electrical system & Cables                                  | ✓         |                                      |
| Cooling system  | ✓         |                                      |
| Steering function   | ✓         |                                      |
| All controls levers function & symbols legible              | ✓         |                                      |
| Capacity plate in place and legible                         | ✓         |                                      |
| All gauges in cab   | ✓         |                                      |
| Over head & foot guard                                      | ✓         |                                      |
| Exhaust system  | ✓         |                                      |
| Side shifting function (if applicable)                      | N/A       |                                      |
| Horn, reverse alarm, rotating warning light                 | ✓         |                                      |
| Lights & indicators   | ✓         |                                      |
| Seat and seat belts   | ✓         |                                      |
| Parking brake and foot brake function                       | ✓         |                                      |
| Fire extinguisher   | ✓         | 02/04/2018 (exp.)                    |
| MPI fork blades, date / report nr. (annually)               | ✓         | 19/12/2017 (exp.) ; O/27546/16/12/01 |
| Mast disassembly (every 4 years)                            | N/A       |                                      |
| General condition   | ✓         |                                      |
| Display markings (SWL, tire pressure, insp. date, due date) | ✓         |                                      |

General comments: Nil

Approved by, Name & Signature: Gishin Thomas

Inspected by, Name & Signature : Madhu Pillai



