



CERTIFICATE OF TEST AND THOROUGH EXAMINATION OF FORKLIFT

Certificate No: MP/35902/17/10/01

Date of Inspection: 29/10/2017

| | | |
|--|--------------------------------|--------------------|
| Name and Address of the Owner: | PREMIER LOGISTICS MUSCAT | |
| Maker & Date of Manufacture: | CATERPILLAR ; 2012 | |
| Place of Inspection: | LR-10 ; AL HUWAISHA | |
| Ref. Standard: | ISO22915-2 /BS EN 1459/PR1708 | |
| Registration No. & Owner No.: | 1002 YD ; TO-2524 | |
| Model No. and Serial No.: | 930H ; CAT0930HADHC04021 | |
| Running hours: | 17413 hrs. | |
| Manufacturer's documentation: | Yes | |
| Date of Previous inspection / cert no: | 21/05/2017 ; MP/34757/17/05/04 | |
| Date of Next inspection: | 28/04/2018 | |
| Date of Previous load test / cert no: | 23/01/2014 ; A/26415/14/01/01 | |
| Date of Next load test: | 28/10/2021 | |
| Availability of operations manual in cabin: | Yes | |
| Availability of daily check report: | Yes | |
| Description of Forklift: Diesel powered hydraulic articulated loader SWL : 6300 kgs @ 600mm load center, | | |
| Test carried out according to tabulated column | | |
| Description of test: Visual inspection & load test carried out. Max. Lifting Height: 3889mm Hydraulic creep : Nil | Test load applied In kgs | S.W.L In kgs |
| | 6900 kg | 6300 kg |
| Conclusion: Fit for its intended use at the time of inspection. | | |

Approved by, Name & Signature: Gishin Thomas

Inspected by, Name & Signature: Madhu Pillai



Annexure of certificate of test & thorough examination of Fork lift

Certificate no: MP/35500/17/10/01

Inspection date: 24/10/2017

| Description | Condition | Remarks |
|---|-----------|-------------------------------|
| Tires, rims, wheel bolts and axles | ✓ | |
| Masts and Back rest , carriage | ✓ | |
| Forks and its extensions, slide end stopper, locks | ✓ | |
| Load chain and its assemblies | N/F | |
| Side rollers and roll over cage | N/F | |
| Safety devices | ✓ | |
| Battery and its connections | ✓ | |
| Hydraulic system & hoses and end fittings | ✓ | |
| Electrical system & Cables | ✓ | |
| Cooling system | ✓ | |
| Steering function | ✓ | |
| All controls levers function & symbols legible | ✓ | |
| Capacity plate in place and legible | ✓ | |
| All gauges in cab | ✓ | |
| Over head & foot guard | ✓ | |
| Exhaust system | ✓ | |
| Side shifting function (if applicable) | N/A | |
| Horn, reverse alarm, rotating warning light | ✓ | |
| Lights & indicators | ✓ | |
| Seat and seat belts | ✓ | |
| Parking brake and foot brake function | ✓ | |
| Fire extinguisher | ✓ | 02/04/2018 |
| MPI fork blades, date / report nr. (annually) | ✓ | 24/07/2017 ; V/34887/17/07/02 |
| Mast disassembly (every 4 years) | ✓ | |
| General condition | ✓ | |
| Display markings (SWL, tire pressure, insp. date, due date) | ✓ | |

General comments: Nil

Approved by, Name & Signature: Gishin Thomas

Inspected by, Name & Signature : Madhu Pillai



