



**CERTIFICATE OF THOROUGH EXAMINATION**

Certificate No: O/41272/19/08/01

Date of Inspection: 22/08/2019

|  |                                 |                    |
|--|---------------------------------|--------------------|
| Name and Address of the Owner:   | TRUCK OMAN RENTAL LLC           |                    |
| Maker & Date of Manufacture:   | CATERPILLAR ; 2012              |                    |
| Place of Inspection:   | YIBAL                           |                    |
| Ref. Standard:   | BS ISO2330 /BS EN 474-3/SP 2275 |                    |
| Registration No. & Owner No.:  | 1002 YD ; TO-2524               |                    |
| Model No. and Serial No.:  | 930H ; CAT0930HADHC04021        |                    |
| Running hours:   | 23553 hrs.                      |                    |
| Manufacturer's documentation:  | OK                              |                    |
| Date of Previous inspection / cert no:   | 24/02/2019 ; O/39666/19/02/01   |                    |
| Date of Next inspection:   | 21/02/2020                      |                    |
| Date of Previous load test / cert no:  | 29/10/2017 ; MP/35902/17/10/01  |                    |
| Date of Next load test:  | 28/10/2021                      |                    |
| Availability of operations manual in cabin:  | OK                              |                    |
| Availability of daily check report:  | OK                              |                    |
| Description:<br>Diesel powered hydraulic operated articulated wheel loader attached with forks SWL : 6357 kgs @ 600mm load center.   |                                 |                    |
| <b>Test carried out according to tabulated column</b>  |                                 |                    |
| Description of test:<br><br>Visual inspection, Functional test & Performance test carried out.<br><br>Max. Lifting Height: 3889mm<br>Hydraulic creep : Nil<br><br>*Fork tine length: 1220mm<br>*static tipping load with level arms & forks, full 40° turn | Test load applied<br>In<br>kgs  | S.W.L<br>In<br>kgs |
|  | 6357 kg                         | 6357 kg*           |
| <b>Conclusion: Fit for its intended use at the time of inspection.</b>   |                                 |                    |

Approved by, Name & Signature: Mr. Gishin Thomas

Inspected by, Name & Signature: Infanso Oswin



## Annexure of certificate of test & thorough examination

Certificate no: O/41272/19/08/01

Inspection date: 22/08/2019

| Description   | Condition      | Remarks              |
|---|----------------|----------------------|
| Tires, rims, wheel bolts and axles                          | Satisfactory   |                      |
| Masts and Back rest , carriage                              | Satisfactory   |                      |
| Forks and its extensions, slide end stopper, locks          | Satisfactory   |                      |
| Load chain and its assemblies                               | Not Applicable |                      |
| Side rollers and roll over cage                             | Satisfactory   |                      |
| Safety devices  | Not Available  |                      |
| Battery and its connections                                 | Satisfactory   |                      |
| Hydraulic system & hoses and end fittings                   | Satisfactory   |                      |
| Electrical system & Cables                                  | Satisfactory   |                      |
| Cooling system  | Satisfactory   |                      |
| Steering function   | Satisfactory   |                      |
| All controls levers function & symbols legible              | Satisfactory   |                      |
| Capacity plate in place and legible                         | Satisfactory   |                      |
| All gauges in cab   | Satisfactory   |                      |
| Over head & foot guard                                      | Satisfactory   |                      |
| Exhaust system  | Satisfactory   |                      |
| Side shifting function (if applicable)                      | Not Applicable |                      |
| Horn, reverse alarm, rotating warning light                 | Satisfactory   |                      |
| Lights & indicators   | Satisfactory   |                      |
| Seat and seat belts   | Satisfactory   |                      |
| Parking brake and foot brake function                       | Satisfactory   |                      |
| Fire extinguisher   | Satisfactory   |                      |
| MPI fork blades, date / report nr. (annually)               | Satisfactory   | 22/08/2019 ; O/41272 |
| Mast disassembly (every 4 years)                            | Not Available  |                      |
| General condition   | Satisfactory   |                      |
| Display markings (SWL, tire pressure, insp. date, due date) | Satisfactory   |                      |

General comments: Nil

Approved by, Name & Signature: Mr. Gishin Thomas

Inspected by, Name & Signature: Infanso Oswin



