



CERTIFICATE OF THOROUGH EXAMINATION

Certificate No: 0/42618/20/02/03

Date of Inspection: 18/02/2020

Name and Address of the Owner:	TRUCK OMAN RENTAL LLC
Maker & Date of Manufacture:	CATERPILLAR ; 2012
Place of Inspection:	AL HUWAISHA
Ref. Standard:	BS ISO2330 /BS EN 474-3/SP 2275
Registration No. & Owner No.:	1002 YD ; TO-2524
Model No. and Serial No.:	930H ; CAT0930HADHC04021
Running hours:	25027 hrs.
Manufacturer's documentation:	OK
Date of Previous inspection / cert no:	29/10/2017 ; O/41272/19/08/01
Date of Next inspection:	17/08/2020
Date of Previous load test / cert no:	29/10/2017 ; O/41272/19/08/01
Date of Next load test:	28/10/2021
Availability of operations manual in cabin:	OK
Availability of daily check report:	OK

Description:
Diesel powered hydraulic operated articulated wheel loader attached with forks SWL : 6357 kgs @ 600mm load center.

Test carried out according to tabulated column		
Description of test:	Test load applied In kgs	S.W.L In kgs
Visual inspection, Functional test & Performance test carried out.	6357 kg	6357 kg*
Max. Lifting Height: 3889mm Hydraulic creep : Nil		
*Fork tine length: 1220mm *static tipping load with level arms & forks, full 40° turn		

Conclusion: Fit for its intended use at the time of inspection.

Approved by, Name & Signature: Mr. Gishin Thomas

Inspected by, Name & Signature: Infanso Oswin



Annexure of certificate of test & thorough examination

Certificate no: 0/42618/20/02/03

Inspection date: 18/02/2020

Description	Condition	Remarks
Tires, rims, wheel bolts and axles	Satisfactory	
Masts and Back rest , carriage	Satisfactory	
Forks and its extensions, slide end stopper, locks	Satisfactory	
Load chain and its assemblies	Not Applicable	
Side rollers and roll over cage	Satisfactory	
Safety devices	Not Available	
Battery and its connections	Satisfactory	
Hydraulic system & hoses and end fittings	Satisfactory	
Electrical system & Cables	Satisfactory	
Cooling system	Satisfactory	
Steering function	Satisfactory	
All controls levers function & symbols legible	Satisfactory	
Capacity plate in place and legible	Satisfactory	
All gauges in cab	Satisfactory	
Over head & foot guard	Satisfactory	
Exhaust system	Satisfactory	
Side shifting function (if applicable)	Not Applicable	
Horn, reverse alarm, rotating warning light	Satisfactory	
Lights & indicators	Satisfactory	
Seat and seat belts	Satisfactory	
Parking brake and foot brake function	Satisfactory	
Fire extinguisher	Satisfactory	
MPI fork blades, date / report nr. (annually)	Satisfactory	18/02/2020 : 0/42618
Mast disassembly (every 4 years)	Not Available	
General condition	Satisfactory	
Display markings (SWL, tire pressure, insp. date, due date)	Satisfactory	

General comments: Nil

Approved by, Name & Signature: Mr. Gishin Thomas

Inspected by, Name & Signature: Infanso Oswin





REPORT OF THOROUGH EXAMINATION

Date of Thorough Examination: 18/02/2020	Report number: 0/4618/20/02/02	Job no: 42618
---	-----------------------------------	------------------

Name and Address of the Owner of the Equipment TRUCK OMAN RENTAL LLC SULTANATE OF OMAN	Address of premises at which the examination was made: YIBAL
--	---

Description and identification of the equipment:

WHEEL LOADER BUCKET

Make : CATERPILLAR

Model No. : 930 H

Owner ID No. : TO-2524

Reg. No. : 1002 YD

Bucket Capacity : 2.3m³

Date of Previous Examination/ cert no: 22/08/2019 O/41272/19/08/03	Date of Next Examination: 17/08/2020
Ref. Standards: LOLER 98	
Comments(If any): NONE	
Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE	
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:(If none state NONE)	
NONE	
IS THIS EQUIPMENT FIT FOR PURPOSE?	YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>

Inspected by, Name & Signature Infando Oswin 	Approved by, Name & Signature Gishin Thomas 	
Name and address of employer of persons making and authenticating this report: SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. lifting@safetyoman.com		