

AN ISO/IEC 17020 ACCREDITED INSPECTION BODY

CERTIFICATE OF THOROUGH EXAMINATION AND TEST

Certificate No: K/51101/23/02/01

Date of Inspection: 04/02/2023

Name and Address of the Owner:	TRUCKOMAN
Maker & Date of Manufacture:	CATERPILLAR:2014
Place of Inspection:	AL HUWAISAH ;PDO RIG NO: 59;RIG NO:T859
Ref. Standard:	BS EN 474-3;BS ISO2330;SP2275
Registration No. & Owner No.:	1002 YD;TO 2524
Model No. and Serial No.:	930H;CAT0930HADHC04021
Running hours:	35865Hrs
Manufacturer's documentation:	In Service Equipment
Date of Previous inspection / cert no:	06/08/2022;MO/49394/22/08/01
Date of Next inspection:	03/08/2023
Date of Previous load test / cert no:	06/08/2022;MO/49394/22/08/01
Date of Next load test:	06/09/2023
Availability of operations manual in cabin:	Available
Availability of daily check report:	Available

Description of Forklift:

Diesel powered hydraulic operated Rubber Tyred Wheel Loader with forks SWL: 6357kgs @ 600 mm load center.

Test carried out according to tabulated column

Description of test:	Test load applied	S.W.L
	In kgs	In kgs
Visual inspection, Functional test & Performance test carried out.		
Max. Lifting Height:3889mm		
Hydraulic creep : Nil	----	6357Kgs
Fork Serial No: 2484663-L8(PAIR) Bucket Serial No:54134863		

Conclusion: Fit for its intended use at the time of inspection. / Refer to checklist- Annexure of certificate

This certificate becomes invalid if any Alteration/Major Repair and modification is done.

This is to certify that the undersigned competent representative, did attend to examine the item described above in accordance to the aforementioned standard. At the time of inspection, the said item were found to be free from flaws, deformations or other defects. The equipment is satisfactory for its intended use within the limits specified and at the time of inspection was found to be satisfactory for further use, provided there is continuous maintenance applied, qualified operators employed and implementation of our remarks and recommendations.

Approved by, Name & Signature Infanso Oswin

Inspected by, Name & Signature : Madhu Pillai



Annexure of certificate of test & thorough examination

Certificate No: K/51101/23/02/01

Date of Inspection: 04/02/2023

Status Legend: S- Satisfactory		NA-Not applicable		F-Findings	CF-Critical Findings	
No.	Description	Status	No.	Description		Status
1	Operations Manual/Catalogue	S	17	All gauges in cab		S
2	Monthly Inspection record	S	18	Overhead & foot guard		S
3	Maintenance records	S	19	Exhaust system		S
4	OEM Specification plate	S	20	Side shifting function (if applicable)		NA
5	Tires, rims, wheel bolts and axles	S	21	Horn, reverse alarm, rotating warning light		S
6	Masts and Back rest , carriage	NA	22	Lights & indicators		S
7	Forks and its extensions, slide end stopper, locks	S	23	Seat and seat belts		S
8	Load chain and its assemblies	NA	24	Parking brake and foot brake function		S
9	Side rollers and roll over cage	S	25	Fire extinguisher		S
10	Safety devices	NA	26	Display markings (SWL, tire pressure, insp. date, due date)		S
11	Battery and its connections	S	27	Full functional test		S
12	Hydraulic system & hoses and end fittings	S	28	Rated load test		S
13	Electrical system & Cables	S	29	Overload test		NA
14	Cooling system	S	30	NDT(if applicable)		F
15	Steering function	S	31	Other Test (if applicable)		NA
16	All controls levers function & symbols legible	S	32	General Condition		S

Details of tools/equipments used: STS-LD-51, STS-LD-59,

Findings/Critical Findings Report

F/CF	No.	Remarks
--	30	Mpi date:06/08/2022;certificate no:MO/49394/22/08/02

