



MAGNETIC PARTICLE INSPECTION REPORT

Date of Through Examination: 21/05/2018	Report number: O/34356/17/04/20/37515/18/05/03	Job no: 37515/18/05/03
Name and Address of owner for whom the thorough examination was made: PREMIER LOGISTICS MUSCAT LLC SULTANATE OF OMAN		Address of premises at which the examination was made: KHAZZAN
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:		
Test Carried Out On Fork, Heel & Toe		
Forklift details		
Make : Caterpillar Model no: 930H Serial no; DHC03393 Owner id: PLM 1524 Registration no: 4828 HR		
Fork details Fork id: F1, F2		
Qty: 1 pair		
Date of Last MPI/ Cert No(If any): 11/04/2017 ; O/34356/17/04/02		
Result of the above test :		
MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONSAT THE TIME OF INSPECTION		
Inspected by, Name & Signature : Qualification : ASNT L2	Infanso Oswin 	Latest date by which next MPI must be carried out: 20/05/2019
Name and address of employer of persons making and authenticating this report: SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. lifting@safetyoman.com		