



# الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م

## SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589; Fax : +968 24590272; Email: stsi@safetyoman.com, Website: www.safetyoman.com  
P.O. Box 3268, Airport Heights P.C. 111, Sultanate of Oman.



### CERTIFICATE OF THOROUGH EXAMINATION AND TEST

Certificate No: O/46122/21/03/03

Date of Inspection: 21/03/2021

|                                             |                                    |
|---------------------------------------------|------------------------------------|
| Name and Address of the Owner:              | Truck Oman Equipment Rental        |
| Maker & Date of Manufacture:                | Caterpillar                        |
| Place of Inspection:                        | YIBAL CATCUS HOIST 51              |
| Ref. Standard:                              | BS EN 474-3; BS ISO 2330           |
| Registration No. & Owner No.:               | 4828 HK & PIM 1524                 |
| Model No. and Serial No.:                   | 930H & CAT093CHT011C03393          |
| Running hours:                              | 28429 Hrs                          |
| Manufacturer's documentation:               | In Services Equipment              |
| Date of Previous inspection / cert no:      | 1/10/2020; N/A/702/20/10/04        |
| Date of Next inspection:                    | 20/09/2021                         |
| Date of Previous load test / cert no:       | 29/04/2020; (L20-AS-040464-10) OIS |
| Date of Next load test:                     | 28/04/2021                         |
| Availability of operations manual in cabin: | Available                          |
| Availability of daily check report:         | Available                          |

Description of Forklift:

Diesel Powered Hydraulic Operated Wheel Loader With Forks SWL: 5000 kgs @ 500 mm load center.

Test carried out according to tabulated column

| Description of test:                                               | Test load applied<br>In<br>kgs | S.W.L<br>In<br>kgs |
|--------------------------------------------------------------------|--------------------------------|--------------------|
| Visual inspection, Functional test & Performance test carried out: |                                |                    |
| Max. Lifting Height: 4049 mm                                       |                                |                    |
| Hydraulic creep: Nil                                               | 5000 Kg                        | 5000 Kg            |
| Fork Serial No: TU917C26343524 (Pair)                              |                                |                    |

Conclusion: Fit for its intended use at the time of inspection. / Refer to checklist- Annexure of certificate

**This certificate becomes invalid if any Alteration/Major Repair and modification is done.**

This is to certify that the undersigned competent representative, did attend to examine the item described above in accordance to the aforementioned standard. At the time of inspection, the said item were found to be free from flaws, deformations or other defects. The equipment is satisfactory for its intended use within the limits specified and at the time of inspection was found to be satisfactory for further use, provided there is continuous maintenance applied, qualified operators employed and implementation of our remarks and recommendations.

Approved by, Name & Signature: Gishin Thomas

Inspected by, Name & Signature: Infanso Oswin



Rev: STSI-SWT-03 Rev:03 Date: 15.05.2017

1/2

This inspection certificate shall not be re-issued, except in full within the approval of the issuing body and the client. Inspection is performed only related to the vehicle and/or the items on the list inspected. Not certified for other vehicles and modifications without an additional inspection.



# الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م

## SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272, Email: stsi@safetyoman.com, Website: www.safetyoman.com  
P.O. Box 3286, Airport Heights P.C. III, Sultanate of Oman.



### Annexure of certificate of test & thorough examination

Certificate No: O/46122/21/03/03

Date of Inspection: 21/03/2021

| Status Legend: S- Satisfactory NA-Not applicable F-Findings CF-Critical Findings |                                                    |                                                      |     |                                                             |        |
|----------------------------------------------------------------------------------|----------------------------------------------------|------------------------------------------------------|-----|-------------------------------------------------------------|--------|
| No.                                                                              | Description                                        | Status                                               | No. | Description                                                 | Status |
| 1                                                                                | Operations Manual/Catalogue                        | S                                                    | 17  | All gauges in cab                                           | S      |
| 2                                                                                | Monthly Inspection record                          | S                                                    | 18  | Overhead & foot guard                                       | S      |
| 3                                                                                | Maintenance records                                | S                                                    | 19  | Exhaust system                                              | S      |
| 4                                                                                | OEM Specification plate                            | S                                                    | 20  | Side shifting function (if applicable)                      | NA     |
| 5                                                                                | Tires, rims, wheel bolts and axles                 | S                                                    | 21  | Horn, reverse alarm, rotating warning light                 | S      |
| 6                                                                                | Masts and Back rest, carriage                      | S                                                    | 22  | Lights & indicators                                         | S      |
| 7                                                                                | Forks and its extensions, slide end stopper, locks | NA                                                   | 23  | Seat and seat belts                                         | S      |
| 8                                                                                | Load chain and its assemblies                      | NA                                                   | 24  | Parking brake and foot brake function                       | S      |
| 9                                                                                | Side rollers and roll over cage                    | NA                                                   | 25  | Fire extinguisher                                           | S      |
| 10                                                                               | Safety devices                                     | S                                                    | 26  | Display markings (SWL, tire pressure, insp. date, due date) | S      |
| 11                                                                               | Battery and its connections                        | S                                                    | 27  | Full functional test                                        | S      |
| 12                                                                               | Hydraulic system & hoses and end fittings          | S                                                    | 28  | Rated load test                                             | S      |
| 13                                                                               | Electrical system & Cables                         | S                                                    | 29  | Overload test                                               | NA     |
| 14                                                                               | Cooling system                                     | S                                                    | 30  | NDT (If applicable)                                         | S      |
| 15                                                                               | Steering function                                  | S                                                    | 31  | Other Test (If applicable)                                  | NA     |
| 16                                                                               | All controls levers function & symbols legible     | S                                                    | 32  | General Condition                                           | S      |
| Details of tools/equipments used: STS-LD-63; STS-VC-7949                         |                                                    |                                                      |     |                                                             |        |
| Findings/Critical Findings Report                                                |                                                    |                                                      |     |                                                             |        |
| F/CF                                                                             | No.                                                | Remarks                                              |     |                                                             |        |
| F                                                                                | 30                                                 | Inspected Date & Cert : 21/03/2021; O/46122/21/03/04 |     |                                                             |        |
|                                                                                  |                                                    |                                                      |     |                                                             |        |





# الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م. SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272, Email: [stsi@safetyoman.com](mailto:stsi@safetyoman.com), Website: [www.safetyoman.com](http://www.safetyoman.com)  
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



## CERTIFICATE OF THOROUGH EXAMINATION & TEST

|                                             |                                    |                  |
|---------------------------------------------|------------------------------------|------------------|
| Date of Thorough Examination:<br>21/03/2021 | Report number:<br>O/46122/21/03/04 | Job no:<br>46122 |
|---------------------------------------------|------------------------------------|------------------|

|                                                                                                    |                                                                                 |
|----------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------|
| Name and Address of the Owner of the Equipment<br>TRUCK OMAN EQUIPMENT RENTAL<br>SULTANATE OF OMAN | Address of premises at which the examination was made:<br>YIBAL CACTUS HOIST 51 |
|----------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------|

| Description and identification of the equipment:                                                                                                                            | Test Load                 | S.W.L                                                                                           |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------|-------------------------------------------------------------------------------------------------|
| Description and Identification of the equipment:<br>MATERIAL HANDLING STINGER<br>Make: CATERPILLAR<br>Model : 930 H<br>Serial no.: 229-9714<br>Owner ID No.: PLM - ST- 1524 | ---<br>2t @ 2 Boom<br>--- | 2.330 t @ 1 <sup>st</sup> boom<br>1.86 t @ 2 <sup>nd</sup> boom<br>1.2 t @ 3 <sup>rd</sup> boom |

Details of tools/equipments used: NA

Date of Previous Examination/ cert no:  
01/10/2020; A/44702/20/10/05

Date of Next Examination:  
20/09/2021

Date of previous Load test/ Cert no:  
26/12/19; MP/42112/19/12/06

Date of Next Load test:  
20/03/2025

Comments(If any): NONE

**RESULT:** The above mentioned equipment was found to be in order for its intended use at the time of inspection.

*This certificate becomes invalid if any Alteration/Major Repair and modification is done.*

This is to certify that the undersigned competent representative, did attend to examine the item described above in accordance to the aforementioned standard. At the time of inspection, the said item were found to be free from flaws, deformations or other defects. The equipment is satisfactory for its intended use within the limits specified and at the time of inspection was found to be satisfactory for further use, provided there is continuous maintenance applied, qualified operators employed and implementation of our remarks and recommendations.

Inspected by, Name & Signature  
Infanso Oswin

Approved by, Name & Signature  
Gishin Thomas



Name and address of employer of persons making and authenticating this report:

Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS  
P.O. Box 3288, Airport Heights PC 111 Sultanate of Oman.  
[lifting@safetyoman.com](mailto:lifting@safetyoman.com)





# الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م. SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel : +968 24502589, Fax : +968 24590272, Email: [stsi@safetyoman.com](mailto:stsi@safetyoman.com), Website: [www.safetyoman.com](http://www.safetyoman.com)  
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



## INSPECTION REPORT

|                                                                                                                                                                                                                                                                                                                                            |                                                    |                                                                                 |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------|---------------------------------------------------------------------------------|
| Date of Thorough Examination:<br>21/03/2021                                                                                                                                                                                                                                                                                                | Report number:<br>O/46122/21/03/05                 | Job no:<br>46122                                                                |
| Name and Address of the Owner of the Equipment<br>TRUCK OMAN EQUIPMENT RENTAL<br>SULTANATE OF OMAN                                                                                                                                                                                                                                         |                                                    | Address of premises at which the examination was made:<br>YIBAL CACTUS HOIST 51 |
| Description and identification of the equipment:<br><u>BUCKET ATTACHMENT FOR WHEEL LOADER</u><br>Make : Caterpillar<br>Vehicle Model no. : 930H<br>Bucket Fleet no. : PLM-BK-1524<br>Bucket Serial no. : 2515413<br>Capacity : 2.1m <sup>3</sup><br><br>Ref Standard: BS EN 474-3;M SP 2275<br>Visual inspection carried out satisfactory. |                                                    |                                                                                 |
| Date of Previous Examination/ cert no:<br>01/10/2020; A/41814/20/10/06                                                                                                                                                                                                                                                                     |                                                    | Date of Next Examination:<br>20/09/2021                                         |
| <b>RESULT:</b> The above mentioned equipment was found to be in order for its intended use at the time of inspection.                                                                                                                                                                                                                      |                                                    |                                                                                 |
| This Inspection Report is issued as requested by the Client and has to be read in conjunction with the OEM certifications or guide lines. This report does not relieve the owner/contractor/end-user from their obligations to keep the equipment periodically maintained and used safely.                                                 |                                                    |                                                                                 |
| Inspected by, Name & Signature<br>Infanso Oswin<br>                                                                                                                                                                                                                                                                                        | Approved by, Name & Signature<br>Gishin Thomas<br> |                                                                                 |
| Name and address of employer of persons making and authenticating this report:<br>Address: <b>SAFETY TECHNICAL SERVICES AND INSPECTIONS</b><br>P.O. Box 3288, Airport Heights PC 111 Sultanate of Oman.<br><a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>                                                              |                                                    |                                                                                 |

