



الشركة الفنية لخدمات السلامة والفحص الفني ش.م.م SAFETY TECHNICAL SERVICES AND INSPECTIONS

Tel :+968 24502589, Fax : +968 24590272. Email: stsi@safetyoman.com, Website: www.safetyoman.com
P.O. Box 3288, Airport Heights P.C. 111, Sultanate of Oman.



CERTIFICATE OF THOROUGH EXAMINATION AND TEST

Certificate No: A/51569/23/05/02

Date of Inspection: 17/05/2023

Name and Address of the Owner:	TRUCK OMAN EQUIPMENT RENTAL LLC
Maker & Date of Manufacture:	CATERPILLAR ; 2011
Place of Inspection:	RIG T 858, RABA
Ref. Standard:	BS EN 474-3/ BS ISO 2330 /SP 2275
Registration No. & Owner No.:	4828 HK ; PLM-1524
Model No. and Serial No.:	930H; CAT0930HCDHC03393
Running hours:	33667 HRS
Manufacturer's documentation:	Satisfactory
Date of Previous inspection / cert no:	21/11/2022: MO/50660
Date of Next inspection:	16/11/2023
Date of Previous load test / cert no:	21/11/2022: MO/50660
Date of Next load test:	20/11/2023
Availability of operations manual in cabin:	Available
Availability of daily check report:	Available

Description of Forklift:

Diesel powered hydraulic operated articulated wheel loader c/w forks SWL : 5000 kgs @ 600 mm load center.

Test carried out according to tabulated column

Description of test:	Test load applied. In kgs	S.W.L In kgs
Visual inspection, Functional test carried out.		
Max. Lifting Height: 3889 mm		
Hydraulic creep : Nil	-----	5000 Kg
FORK SERIAL NO: 195-6935 (PAIR)		

Conclusion: Fit for its intended use at the time of inspection. / Refer to checklist- Annexure of certificate

This certificate becomes invalid if any Alteration/Major Repair and modification is done.

This is to certify that the undersigned competent representative, did attend to examine the item described above in accordance to the aforementioned standard. At the time of inspection, the said item were found to be free from flaws, deformations or other defects. The equipment is satisfactory for its intended use within the limits specified and at the time of inspection was found to be satisfactory for further use, provided there is continuous maintenance applied, qualified operators employed and implementation of our remarks and recommendations.

Approved by, Name & Signature: INFANSO OSWIN

Inspected by, Name & Signature: MOHAMMED ANAZ





Annexure of certificate of test & thorough examination

Certificate No: A/51569/23/05/02

Date of Inspection: 17/05/2023

Status Legend:		S- Satisfactory	NA-Not applicable	F-Findings	CF-Critical Findings	
No.	Description	Status	No.	Description		Status
1	Operations Manual/Catalogue	S	17	All gauges in cab		S
2	Monthly Inspection record	S	18	Overhead & foot guard		S
3	Maintenance records	S	19	Exhaust system		S
4	OEM Specification plate	S	20	Side shifting function (if applicable)		NA
5	Tires, rims, wheel bolts and axles	F	21	Horn, reverse alarm, rotating warning light		S
6	Masts and Back rest , carriage	NA	22	Lights & indicators		S
7	Forks and its extensions, slide end stopper, locks	S	23	Seat and seat belts		S
8	Load chain and its assemblies	NA	24	Parking brake and foot brake function		S
9	Side rollers and roll over cage	NA	25	Fire extinguisher		S
10	Safety devices	S	26	Display markings (SWL, tire pressure, insp. date, due date)		S
11	Battery and its connections	S	27	Full functional test		S
12	Hydraulic system & hoses and end fittings	S	28	Rated load test		NA
13	Electrical system & Cables	S	29	Overload test		NA
14	Cooling system	S	30	NDT(If applicable)		F
15	Steering function	S	31	Other Test (If applicable)		NA
16	All controls lever's function & symbols legible	S	32	General Condition		S

Details of tools/equipment used: STS-LD-77,78

Findings/Critical Findings Report

F/CF	No.	Remarks
F	30	FORK MPI DONE - 21/11/2022 ; MO/50660/22/11/02
F	5	RECOMMENDED TO USE SAME TIRE PATTERN ON SAME AXLE.