



CERTIFICATE OF TEST & THOROUGH EXAMINATION, LOAD TEST OF A FORKLIFT

IN-SERVICE INSPECTION

Identification No.:SV/JUN20/105 **Our Ref.No.:**AN 010 **Date of inspection:**26/06/2020

Date of issue :28/06/2020

Name and Address of the Owner:	TRUCK OMAN EQUIPMENT RENTAL. LLC
Maker & Date of Manufacture:	CATTERPILLER & 2012
Place of Inspection:	BP- KHAZZAN
Internationally accepted Ref. Standard	BS EN 1459-1:2017,ISO 3691-1:2015,ISO 22915-2:2018
Specification of Regional Regulatory Authority	PDO SP-2275:2019
Registration No.& Owner No.:	Reg. No.: 2517 YS & Owner no.: PLM-1528
Model No. and Serial No.:	Model no.: 930H & Sr.no.: CAT0930HCDHC03397
Manufacturer's documentation:	Available
Date of Previous Inspection / cert no:	26/12/2019 & Cert.No.: MP/42112/19/12/01 (STS)
Date of Next Inspection:	25/12/2020
Date of Previous load test/ cert no:	02/08/2016 : A/32198/16/08/01
Date of load test	26/06/2020
Date of Next load test:	25/06/2024
Availability of operations manual in cabin:	Available
Availability of daily check report:	Available

Description of Forklift: Diesel powered hydraulic operated articulated forklift SWL: 5,000 kgs. @600mm load center
Maximum Height of lift: 3889 mm

Description of test:	Test load applied In kgs	S.W.L In kgs
Load test & Performance test carried out as per tabulated column Load cell used: Nil Calibration certificate: N/A Hydraulic creep : Nil	5500	5,000

Conclusion: Fit for its intended use

Approved by GM/OM/EM,

Name & signature: Jaban Pourjhangiri

Inspected by,

Name & signature: Abdul Aziz

OTIS/CERT/FLT/01

Rev no. 01

Rev Date: 06.10.2019

Page 1 of 2



Annexure of Certificate of Test & Thorough Examination of a Forklift

Identification No.: SV/JUN20/105 Our Ref.No.: AN 010 Date of inspection: 26/06/2020

Date of issue : 28/06/2020

Description	Condition	Remarks
Tires, rims, wheel bolts and axles	✓	
Masts and Back rest , carriage	✓	
Forks and its extensions, slide end stopper, locks	✓	
Load chain and its assemblies	X	Not Applicable
Side rollers and roll over cage	X	Not Applicable
Safety devices	✓	
Battery and its connections	✓	
Hydraulic system & hoses and end fittings	✓	
Electrical system & Cables	✓	
Cooling system	✓	
Steering function	✓	
All controls levers function & symbols legible	✓	
Capacity plate in place and legible	✓	
All gauges in cab	✓	
Overhead & foot guard	✓	
Exhaust system	✓	
Side shifting function (if applicable)	X	Not fitted
Horn, reverse alarm, rotating warning light	✓	
Lights & indicators	✓	
Seat and seat belts	✓	
Parking brake and foot brake function	✓	
Fire extinguisher	✓	
MPI fork blades, date / report nr. (annually)	✓	Done on: 25/12/2019 & crt no: MP.42112.19.12.2 (STS)
Mast disassembly (every 4 years)	X	
General condition	✓	
Display markings (SWL, tire pressure, insp. date, due date)	✓	

General comments: All the Conditions mentioned above found, at the time of Inspection.
Fit for its intended use

Approved by GM/OM/TM

Name & signature: Jahar Pourahangiri

Inspected by,

Name & signature: Abdul Anzar

OTIS/CERT/FLT/01

Rev no. 01

Rev Date: 06.10.2019

Page 2 of 2