



**CERTIFICATE OF TEST AND THOROUGH EXAMINATION**

Certificate No: O/40832/19/07/01

Date of Inspection: 02/07/2019

|   |                                 |                    |
|---|---------------------------------|--------------------|
| Name and Address of the Owner:  | TRUCK OMAN EQUIPMENT RENTAL LLC |                    |
| Maker & Date of Manufacture:  | CATERPILLAR ; 2012              |                    |
| Place of Inspection:  | AL HUWAISHA                     |                    |
| Ref. Standard:  | BS EN 474-3/SP 2275             |                    |
| Registration No. & Owner No.:   | 2517 YS ; PLM-1528              |                    |
| Model No. and Serial No.:   | 930H ; CAT930HCDHC03397         |                    |
| Running hours:  | 19485.2 hrs.                    |                    |
| Manufacturer's documentation:   | Yes                             |                    |
| Date of Previous inspection / cert no:  | 09/01/2019 ; K/39508/19/01/01   |                    |
| Date of Next inspection:  | 01/01/2020                      |                    |
| Date of Previous load test / cert no:   | 07/08/2016 ; A/32198/16/08/01   |                    |
| Date of Next load test:   | 01/08/2020                      |                    |
| Availability of operations manual in cabin:   | Yes                             |                    |
| Availability of daily check report:   | Yes                             |                    |
| Description:<br>Diesel powered hydraulically operated articulated wheel loader c/w forks SWL : 5000kgs @ 600mm load center, |                                 |                    |
| Test carried out according to tabulated column  |                                 |                    |
| Description of test:  | Test load applied<br>In<br>kgs  | S.W.L<br>In<br>kgs |
| Visual inspection, Functional test & Performance test carried out found satisfactory  | 5 t                             | 5 t                |
| Max. Lifting Height: 3889mm   |                                 |                    |
| Hydraulic creep : Nil   |                                 |                    |
| Conclusion: Fit for its intended use at the time of inspection.   |                                 |                    |

Approved by, Name & Signature: Gishin Thomas

Inspected by, Name & Signature : Infanso Oswin



## Annexure of certificate of test & thorough examination

Certificate no: O/40832/19/07/01

Inspection date: 02/07/2019

| Description   | Condition    | Remarks                       |
|---|--------------|-------------------------------|
| Tires, rims, wheel bolts and axles                          | Satisfactory |                               |
| Masts and Back rest , carriage                              | Satisfactory |                               |
| Forks and its extensions, slide end stopper, locks          | Satisfactory |                               |
| Load chain and its assemblies                               | Satisfactory |                               |
| Side rollers and roll over cage                             | Satisfactory |                               |
| Safety devices  | Satisfactory |                               |
| Battery and its connections                                 | Satisfactory |                               |
| Hydraulic system & hoses and end fittings                   | Satisfactory |                               |
| Electrical system & Cables                                  | Satisfactory |                               |
| Cooling system  | Satisfactory |                               |
| Steering function   | Satisfactory |                               |
| All controls levers function & symbols legible              | Satisfactory |                               |
| Capacity plate in place and legible                         | Satisfactory |                               |
| All gauges in cab   | Satisfactory |                               |
| Over head & foot guard                                      | Satisfactory |                               |
| Exhaust system  | Satisfactory |                               |
| Side shifting function (if applicable)                      | N/A          |                               |
| Horn, reverse alarm, rotating warning light                 | Satisfactory |                               |
| Lights & indicators   | Satisfactory |                               |
| Seat and seat belts   | Satisfactory |                               |
| Parking brake and foot brake function                       | Satisfactory |                               |
| Fire extinguisher   | Satisfactory |                               |
| MPI fork blades, date / report nr. (annually)               | Satisfactory | 13/11/2018 ; O/38758/18/11/11 |
| Mast disassembly (every 4 years)                            | N/A          |                               |
| General condition   | Satisfactory |                               |
| Display markings (SWL, tire pressure, insp. date, due date) | Satisfactory |                               |

General comments: NONE

Approved by, Name & Signature: Gishin Thomas

Inspected by, Name & Signature : Infanso Oswin



