



## MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 20/10/2016	Report number: O/33109/16/10/02	Job no: 33109
Name and Address of owner for whom the thorough examination was made:  PREMIER LOGISTICS SULTANATE OF OMAN	Address of premises at which the examination was made:  JIFFNAIN	
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:  <b><u>TESTED ON FORK TOE, HELL &amp; FORK HOLD BRACKET</u></b>  Fork ID No. : F1 & F2 Owner ID No. : PLM-1523 Dimensions : L x W x H – 1200 x 740 x 120mm Thickness : 50 x 50 x 40 x 10mm  Qty: 1 pair  Date of Last MPI/ Cert No( If any): Nil		
Result of the above test :  MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		
Inspected by, Name & Signature :  Qualification : ASNT L2	Infanso Oswin 	Latest date by which next MPI must be carried out:  19/10/2017
Name and address of employer of persons making and authenticating this report:  SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		