



## MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 22/09/2019	Report number: MP/40945/19/09/04	Job no: 40945
Name and Address of owner for whom the thorough examination was made:  PREMIER LOGISTICS SULTANATE OF OMAN		Address of premises at which the examination was made:  YIBAL (#50)
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:  <b>FORK MPI ON HEEL AND HOLDING BRACKET</b>		
Make : CATERPILLAR		
Owner ID No. : PLM-1520		
Fork Dimension : LxWxH – 1200mm x 150mm x 700mm		
Qty: 1no		
Date of Last MPI/ Cert No( If any): 19/09/2018 ; MP/37750		
Result of the above test :  <b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONSAT THE TIME OF INSPECTION</b>		
Inspected by, Name & Signature :  Qualification : ASNT L2	Madhu Pillai 	Latest date by which next MPI must be carried out:  21/09/2020
Name and address of employer of persons making and authenticating this report:  SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		