



INSPECTION REPORT

Date of Thorough Examination: 22/09/2019	Report number: MP/40945/19/09/02	Job no: 40945
---	-------------------------------------	------------------

Name and Address of the Owner of the Equipment PREMIER LOGISTICS SULTANATE OF OMAN	Address of premises at which the examination was made: YIBAL (#50)
--	--

Description and identification of the equipment:

FORKLIFT BUCKET

Make : CATERPILLAR

Serial No. : 2100043220

Plant ID : PLM-1520

Capacity : 2.1m³

Visual inspection carried out and Witnessed the functional test satisfactory.

Date of Previous Examination/ cert no: 19/09/2018 ; MP/37750/18/09/03	Date of Next Examination: 21/03/2020
--	---

Ref. Standards: AS per manufacturer specifications.

Comments (If any): Inspected as per customer requirement

Particulars of any repair, renewal or alteration required to remedy the defect identified above:
NONE

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none state NONE)

NONE

IS THIS EQUIPMENT FIT FOR PURPOSE AT THE TIME OF INSPECTION?

YES NO

Inspected by, Name & Signature: Madhu Pillai 	Approved by, Name & Signature Gishin Thomas 	
Name and address of employer of persons making and authenticating this report: SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. lifting@safetyoman.com		



الشركة الفنية لخدمات السلامة ش.م.م
SAFETY *technical* SERVICES CO. LTD.



CERTIFICATE OF THOROUGH EXAMINATION & TEST


Date of Thorough Examination: 22/09/2019	Report number: MP/40945/19/09/03	Job no: 40945
---	-------------------------------------	------------------

Name and Address of the Owner of the Equipment PREMIER LOGISTICS SULTANATE OF OMAN		Address of premises at which the examination was made: YIBAL (#50)	
Description and identification of the equipment: MATERIAL HANDLING ARAM		Test Load	S.W.L
Make : CATERPILLAR		----	1060 kg @ 1520mm
Model : 229-9714		----	830 kg @ 2630mm
Serial No. : MSC 110617		----	680 kg @ 3660mm
Reg. No. : 1460 ML			
Plant ID No. : PLM-1520			
Date of Previous Examination/ cert no: 19/09/2018 ; MP/37750/18/09/02	Date of Next Examination: 21/03/2020		
Date of previous Load test/ Cert no: 05/04/2018 ; G/36875	Date of Next Load test: 04/04/2022		
Ref. Standards: ISO 13284- SP 2275			
Comments (If any): NONE			
Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE			
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none state NONE) NONE			
IS THIS EQUIPMENT FIT FOR PURPOSE AT THE TIME OF INSPECTION?		YES	✓ NO

Inspected by, Name & Signature Madhu Pillai 	Approved by, Name & Signature Gishin Thomas 	
Name and address of employer of persons making and authenticating this report: SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. lifting@safetyoman.com		



MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 22/09/2019	Report number: MP/40945/19/09/04	Job no: 40945
Name and Address of owner for whom the thorough examination was made: PREMIER LOGISTICS SULTANATE OF OMAN		Address of premises at which the examination was made: YIBAL (#50)
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment: <u>FORK MPI ON HEEL AND HOLDING BRACKET</u>		
Make : CATERPILLAR		
Owner ID No. : PLM-1520		
Fork Dimension : LxWxH – 1200mm x 150mm x 700mm		
Qty: 1no		
Date of Last MPI/ Cert No(If any): 19/09/2018 ; MP/37750		
Result of the above test : <u>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</u>		
Inspected by, Name & Signature : Qualification : ASNT L2	Madhu Pillai 	Latest date by which next MPI must be carried out: 21/09/2020
Name and address of employer of persons making and authenticating this report: SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. lifting@safetyoman.com		