



### CERTIFICATE OF TEST AND THOROUGH EXAMINATION

Certificate No: O/35527/17/10/01

Date of Inspection: 02/10/2017

Name and Address of the Owner:	PREMIER LOGISTICS MUSCAT	
Maker & Date of Manufacture:	CATERPILLAR	
Place of Inspection:	FAHUD RIG#72	
Ref. Standard:	ISO22915-2 /BS EN 1459/PR1708	
Registration No. & Owner No.:	1460 ML ; PLM-1520	
Model No. and Serial No.:	CAT 930H ;CAT0930HTDHC03121	
Running hours:	18121 hrs.	
Manufacturer's documentation:	OK	
Date of Previous inspection / cert no:	03/04/2017 ; RA/34220/17/04/03	
Date of Next inspection:	01/04/2018	
Date of Previous load test / cert no:	25/11/2015 ; MP/30484/15/11/1	
Date of Next load test:	24/11/2019	
Availability of operations manual in cabin:	OK	
Availability of daily check report:	OK	
Description of Forklift: Diesel powered hydraulic articulated wheel loader c/w fork SWL : 5500 kgs @ 600mm load center,		
<b>Test carried out according to tabulated column</b>		
Description of test: Visual inspection, Functional test & Performance test carried out.  Max. Lifting Height: 3889mm  Hydraulic creep : Nil	Test load applied In kgs	S.W.L In kgs
	<b>5500 kg</b>	<b>5500 kg</b>
<b>Conclusion: Fit for its intended use at the time of inspection.</b>		

Approved by, Name & Signature: Gishin Thomas

Inspected by, Name & Signature : Infanso Oswin



## Annexure of certificate of test & thorough examination of Fork lift

Certificate No: O/35527/17/10/01

Date of Inspection: 02/10/2017

Description	Condition	Remarks
Tires, rims, wheel bolts and axles	✓	
Masts and Back rest , carriage	✓	
Forks and its extensions, slide end stopper, locks	✓	
Load chain and its assemblies	N/A	
Side rollers and roll over cage	N/A	
Safety devices	N/A	
Battery and its connections	✓	
Hydraulic system & hoses and end fittings	✓	
Electrical system & Cables	✓	
Cooling system	✓	
Steering function	✓	
All controls levers function & symbols legible	✓	
Capacity plate in place and legible	✓	
All gauges in cab	✓	
Over head & foot guard	✓	
Exhaust system	✓	
Side shifting function (if applicable)	Nil	
Horn, reverse alarm, rotating warning light	✓	
Lights & indicators	✓	
Seat and seat belts	✓	
Parking brake and foot brake function	✓	
Fire extinguisher	✓	
MPI fork blades, date / report nr. (annually)	✓	02/10/2017
Mast disassembly (every 4 years)	Nil	
General condition	✓	
Display markings (SWL, tire pressure, insp. date, due date)	✓	

General comments: Nil

Approved by, Name & Signature: Gishin Thomas

Inspected by, Name & Signature : Infanso Oswin



