



CERTIFICATE OF TEST AND THOROUGH EXAMINATION

Certificate No: A/40252/19/04/01

Date of Inspection: 10/04/2019

Name and Address of the Owner:	PREMIER LOGISTICS MUSCAT	
Maker & Date of Manufacture:	CATERPILLAR ; 2012	
Place of Inspection:	FAHUD ; RIG-72	
Ref. Standard:	ISO22915-2 /BS EN 1459/SP 2275	
Registration No. & Owner No.:	2516 YS ; PLM 1527	
Model No. and Serial No.:	930H ; CAT0930HTDHC04012	
Running hours:	20676 hrs.	
Manufacturer's documentation:	Yes	
Date of Previous inspection / cert no:	06/11/2018 ; A/38635/18/11/01	
Date of Next inspection:	09/10/2019	
Date of Previous load test / cert no:	28/09/2016 ; A/32694	
Date of Next load test:	27/09/2020	
Availability of operations manual in cabin:	Yes	
Availability of daily check report:	Yes	
Description : Diesel powered hydraulic articulated wheel loader c/w fork SWL : 5000 kgs @ 600mm load center,		
Test carried out according to tabulated column		
Description of test: Visual inspection, Functional test & Light load test carried out. Max. Lifting Height: 3889mm Hydraulic creep : Nil Fork S/N: 2378330-L8 (pair) <u>Bucket Attachment :</u> Serial no. : 21000510933 Capacity : 2.7m ³	Test load applied In kgs	S.W.L In kgs
	----	5000 kg @ 600mm load centre
Conclusion: Fit for its intended use at the time of inspection.		

Approved by, Name & Signature: Gishin Thomas

Inspected by, Name & Signature : Mohammed Anaz



Annexure of certificate of test & thorough examination

Certificate No: A/40252/19/04/01

Date of Inspection: 10/04/2019

Description	Condition	Remarks
Tires, rims, wheel bolts and axles	Satisfactory	
Masts and Back rest , carriage	Satisfactory	
Forks and its extensions, slide end stopper, locks	Satisfactory	
Load chain and its assemblies	N/A	
Side rollers and roll over cage	N/A	
Safety devices	Satisfactory	
Battery and its connections	Satisfactory	
Hydraulic system & hoses and end fittings	Satisfactory	
Electrical system & Cables	Satisfactory	
Cooling system	Satisfactory	
Steering function	Satisfactory	
All controls levers function & symbols legible	Satisfactory	
Capacity plate in place and legible	Satisfactory	
All gauges in cab	Satisfactory	
Over head & foot guard	Satisfactory	
Exhaust system	Satisfactory	
Side shifting function (if applicable)	N/A	
Horn, reverse alarm, rotating warning light	Satisfactory	
Lights & indicators	Satisfactory	
Seat and seat belts	Satisfactory	
Parking brake and foot brake function	Satisfactory	
Fire extinguisher	Satisfactory	
MPI fork blades, date / report nr. (annually)	Satisfactory	23/03/2019 ; O/39687
Mast disassembly (every 4 years)	Nil	
General condition	Satisfactory	
Display markings (SWL, tire pressure, insp. date, due date)	Satisfactory	
Details of tools/equipments used: Measuring tape (STS-LD-77) ; Anemometer (STS-LD-57).		

General comments: NONE

Approved by, Name & Signature: Gishin Thomas

Inspected by, Name & Signature : Mohammed Anaz



