



**CERTIFICATE OF TEST & THOROUGH EXAMINATION OF A FORKLIFT**

**IN-SERVICE INSPECTION**

**Ident/Cert. No.: RK/FEB22/102**      **Our Ref. No. : RK 1165**      **Date of inspection: 09/02/2022**

**Date of issue : 11/02/2022**

Name and Address of the Owner:	<b>Truck Oman LLC.</b>
Maker & Date of Manufacture:	Caterpillar
Place of Inspection:	Qarat Al-Milh (Hoist 52)
Internationally accepted Ref. Standard	BS EN 1459-1:2017+A1:2020, BS EN ISO 3691-1:2015+A1:2020 ISO 22915-2:2018
Specification of Regional Regulatory Authority	PDO SP-2275:2021
Registration No.& Owner No.:	<b>Reg. No.: 2516 YS &amp; Owner No.: PLM 1527</b>
Model No. and Serial No.:	Model no.: 930 H & Serial no.: CAT0930HHDHCO4118
Running hours:	29980 hrs
Manufacturer's documentation:	Available
Date of Previous Inspection / cert no:	14/09/2021 & Cert. No.: KJ/SEP21/089(OTIS)
Date of Inspection:	<b>09/08/2022</b>
Date of Next Inspection:	<b>08/08/2022</b>
Date of load test:	<b>14/09/2021</b>
Date of Next load test:	<b>13/09/2025</b>
Availability of operations manual in cabin:	Available
Availability of daily check report:	To be placed in cabin

Description of Forklift: Diesel powered hydraulic Articulated forklift SWL : 6,000 kg @ 500mm load center  
Maximum Height of lift: 3800 mm

Description of test:	Test load applied	S.W.L
	In kgs	In kgs
Performance test, Visual Inspection & fully functional test carried out as per tabulated column Load cell used: Yes	5,800	6,000
Hydraulic creep : Nil		

Conclusion: Fit for its intended use

Approved by GM/OM/TM,

Inspected by,

Name & signature: Jahan Pourjahanian

Name & signature: Rishad K A

OTIS/CERT/FLT/01

Rev no. 02

Rev Date: 07.01.2021

Page 1 of 2



## **Annexure of Certificate of Test & Thorough Examination of a Forklift**

**Ident/Cert. No.: RK/FEB22/102**

**Our Ref. No. : RK 1165**

Date of inspection: 09/02/2022

Date of issue : 11/02/2022

Description	Condition	Remarks
Tires, rims, wheel bolts and axles	✓	
Masts and Back rest , carriage	✓	
Forks and its extensions, slide end stopper, locks	✓	
Wear & Shank angle	✓	Shank Angle 91°
Load chain and its assemblies	X	Not Fitted
Side rollers and roll over cage	✓	
Safety devices	✓	
Battery and its connections	✓	
Hydraulic system & hoses and end fittings	✓	
Electrical system & Cables	✓	
Cooling system	✓	
Steering function	✓	
All controls levers function & symbols legible	✓	
Capacity plate in place and legible	✓	
All gauges in cab	✓	
Overhead & foot guard	✓	
Exhaust system	✓	
Side shifting function (if applicable)	X	Not Fitted
Horn, reverse alarm, rotating warning light	✓	
Lights & indicators	✓	
Seat and seat belts	✓	
Parking brake and foot brake function	✓	
Fire extinguisher	✓	
MPI fork blades, date / report nr. (annually)	✓	Cert.no.: KJ/SEP21/090 valid until 13/09/2022
Mast disassembly (every 4 years)	✓	
General condition	✓	
Display markings (SWL, tire pressure, insp. date, due date)	✓	

**General comments:** All the Conditions mentioned above found, at the time of Inspection.

### Fit for its intended use

Inspected by:

Approved by GM/OM/TM,

Name & signature: Jahan Pourjahanipour

Name & signature: Rishad K A

OTIS / CERT / ELT / 01

Rev Date: 07.01.2021

Page 2 of 2

