





MAGNETIC PARTICLE INSPECTION REPORT

| | | |
|---|--|---|
| Date of Thorough Examination: 09/04/2019 | Report number: A/39149/19/04/02 | Job no: 39149 |
| Name and Address of owner for whom the thorough examination was made: PREMIER LOGISTICS MUSCAT LLC SULTANATE OF OMAN | Address of premises at which the examination was made: FAHUD | |
| Method: WET Surface Condition: Acceptable | Material: Carbon Steel Equipment: Permanent magnet Yoke | Test temperature: Ambient |
| Area Inspected (tick the appropriate box): <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others | | |
| WHITE CONTRAST PAINT: Magnavis WCP | MAGNETISING METHOD: Wet suspension black ink | |
| BLACK MAGNETIC INK: Magnaflux 7HF | ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1 | |
| Description and identification of the equipment: <u>FORK HEEL AND HOLDING BRACKET</u> Make : CATERPILLAR Reg. No. : 3242 ML Fleet No. : PLM-1525 Fork Serial no. : 1104208L (pair) Qty: 1 pair Date of Last MPI/ Cert No(If any): 21/05/2018 ; O/37516/18/05/02 | | |
| Result of the above test : MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION | | |
| Inspected by, Name & Signature : Qualification : ASNT L2 | Mohammed Anaz  | Latest date by which next MPI must be carried out: 08/04/2020 |
| Name and address of employer of persons making and authenticating this report: SAFETY TECHNICAL SERVICES PO BOX 3288. SEEB. PC 111 MUSCAT. lifting@safetyoman.com | |  |