

## MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 22/09/2020	Report number: K/44565/20/09/02	Job no: 44565
Name and Address of the Owner of the Equipment PREMIER LOGISTICS MUSCAT LLC SULTANATE OF OMAN		Address of premises at which the examination was made: NIZWA
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:  <b>FORK HEEL AND HOLDING BRACKET</b>		
Make : Caterpillar Reg. No. : 3242 ML Fleet No. : PLM-1525 Fork Serial no. : 1104203L (pair)		
Qty: 1 pair  Date of Last MPI/ Cert No( If any): 09/04/19; A/39149/19/04/02		
Result of the above test :  <b>MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION</b>		

Inspected by, Name & Signature : Koshy Mathew		Latest date by which next MPI must be carried out: 21/09/2021
Qualification : ASNT L2		
Name and address of employer of persons making and authenticating this report:  <b>Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS</b> <b>P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman.</b> <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		

