

## MAGNETIC PARTICLE INSPECTION REPORT

Date of Thorough Examination: 30/03/2022	Report number: AB/48664/22/03/03	Job no: 48664
Name and Address of the Owner of the Equipment  TRUCK OMAN EQUIPMENT RENTAL SULTANATE OF OMAN		Address of premises at which the examination was made:  JIFNAIN
Method: WET Surface Condition: Acceptable	Material: Carbon Steel Equipment: Permanent magnet Yoke	Test temperature: Ambient
Area Inspected ( tick the appropriate box):  <input checked="" type="checkbox"/> Weldment areas <input checked="" type="checkbox"/> Stress Areas <input type="checkbox"/> Full Body <input type="checkbox"/> Others		
WHITE CONTRAST PAINT: Magnavis WCP	MAGNETISING METHOD: Wet suspension black ink	
BLACK MAGNETIC INK: Magnaflux 7HF	ACCEPTANCE CODE: ASME V ARTICLE 7 , ASTM E709 ,AWS D1.1	
Description and identification of the equipment:  <b>FORK HEEL AND HOLDING BRACKET</b>		
Make : Caterpillar		
Reg. No. : 3242 ML		
Fleet No. : PLM-1525		
Fork Serial no. : 1104203L (pair)		
Qty: 1 pair		
Date of Last MPI/ Cert No( If any): 09/04/19; A/39149/19/04/02		
Result of the above test :		
MPI TEST CARRIED OUT SATISFACTORILY, FOUND NO RELEVANT INDICATIONS AT THE TIME OF INSPECTION		

Inspected by, Name & Signature : MOHAMMED ANAZ		Latest date by which next MPI must be carried out: 29/03/2023
Qualification : ASNT L2		
Name and address of employer of persons making and authenticating this report:  Address: SAFETY TECHNICAL SERVICES AND INSPECTIONS P.O. Box 3288. Airport Heights PC 111 Sultanate of Oman. <a href="mailto:lifting@safetyoman.com">lifting@safetyoman.com</a>		

