



CERTIFICATE OF THOROUGH EXAMINATION AND TEST OF FORKLIFT

Certificate No: A/39149/19/04/01

Date of Inspection: 09/04/2019

Name and Address of the Owner:	PREMIER LOGISTICS	
Maker & Date of Manufacture:	CATERPILLAR ; 2011	
Place of Inspection:	FAHUD	
Ref. Standard:	ISO22915-2 /BS EN 1459	
Registration No. & Owner No.:	3242 ML ; PLM-1525	
Model No. and Serial No.:	DP 100N ; T36A-10496	
Running hours:	11761 hrs.	
Manufacturer's documentation:	Available	
Date of Previous inspection / cert no:	01/11/2018 ; O/38498/18/11/1	
Date of Next inspection:	08/10/2019	
Date of Previous load test / cert no:	07/06/2017 ; MP/34770/17/06/01	
Date of Next load test:	06/06/2021	
Availability of operations manual in cabin:	Available	
Availability of daily check report:	Available	
Description of Forklift: Diesel powered hydraulic counter balanced fork lift with side shifter SWL : 9800 kgs @ 600mm load center,		
Test carried out according to tabulated column		
Description of test: Visual inspection, Functional test & Performance test carried out.	Test load applied In kgs	S.W.L In kgs
	----	9800 kg @ 600mm
Max. Lifting Height: 4500mm		
Hydraulic creep : Nil		
Fork ID No. : 1104208L (pair)		
Conclusion: Fit for its intended use at the time of inspection.		

Approved by, Name & Signature: Mr. Gishin Thomas

Inspected by, Name & Signature: Infanso Oswin

Gishin Thomas



Infanso Oswin



Annexure of certificate of test & thorough examination of Fork lift

Certificate no: A/39149/19/04/01

Inspection date: 09/04/2019

Description	Condition	Remarks
Tires, rims, wheel bolts and axles	Satisfactory	
Masts and Back rest , carriage	Satisfactory	
Forks and its extensions, slide end stopper, locks	Satisfactory	
Load chain and its assemblies	Satisfactory	
Side rollers and roll over cage	Satisfactory	
Safety devices	N/A	
Battery and its connections	Satisfactory	
Hydraulic system & hoses and end fittings	Satisfactory	
Electrical system & Cables	Satisfactory	
Cooling system	Satisfactory	
Steering function	Satisfactory	
All controls levers function & symbols legible	Satisfactory	
Capacity plate in place and legible	Satisfactory	
All gauges in cab	Satisfactory	
Over head & foot guard	Satisfactory	
Exhaust system	Satisfactory	
Side shifting function (if applicable)	Satisfactory	
Horn, reverse alarm, rotating warning light	Satisfactory	
Lights & indicators	Satisfactory	
Seat and seat belts	Satisfactory	
Parking brake and foot brake function	Satisfactory	
Fire extinguisher	Satisfactory	
MPI fork blades, date / report nr. (annually)	Satisfactory	09/04/2019
Mast disassembly (every 4 years)	N/A	
General condition	Satisfactory	
Display markings (SWL, tire pressure, insp. date, due date)	Satisfactory	
Details of tools/equipments used: Measuring tape (STS-LD-77) ; Anemometer (STS-LD-77).		

General comments: NONE

Approved by, Name & Signature: Mr. Gishin Thomas

Inspected by, Name & Signature: Infanso Oswin

